

SURVEY &  
REMONUMENTATION

7-  
2 MAY 28 1997

COMMISSION

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Kalamazoo Located in: Corner Code #  
Texas (County) Twp.  
1. Public Land Survey T 3S R 12W A-02  
T R  
T R  
T R  
2. Property Controlling S T R  
in Section S T R  
3. Miscellaneous S T R  
Property in Sec. S T R

STATE OF MICHIGAN  
COUNTY OF KALAMAZOO  
RECORDS FOR RECORD  
96 OCT 18 AM 11 32  
CLERK - REGISTER  
2 PAGE 073  
Register of Deeds Stamp & File Number

4. Lot No. , Recorded Plat  
5. Private Claims

I, Robert E. Snell, in a field survey on March 3, 19 96 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

A. Description of original monument and accessories and/or subsequent restoration:

This corner not set by original United States Government Surveyors.

1874: Ed Strong, County Surveyor; West 1/4 post Y. Oak 6" N. 45° W. 1½ lks. Stone at proportional distance.

RATIFIED  
BY KALAMAZOO COUNTY  
REMONUMENTATION  
PEER GROUP  
5-16-1996

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

1992: Thomas Chettleburgh, RLS #16036; LCRC, L-1, P-960 found stone with "x" on top 1.33' West of Township line and 187.47' North of West 1/4 corner (concrete monument) Sec. 6 (3-13).  
Nail S. side 30" Stump N 90° W. 1.30' Nail SW. side 16" Oak S. 30° E. 54.28'  
Nail E. side 12" Sassafras N. 00° E. 18.14' East line Sec. 1 (3-13) East 1.33'  
Nail SW. side 13" Sassafras S. 58° E. 71.00' Conc. Mon. E½ cor. Sec. 1(3-13) S. 187.47'

1996: Found stone with "x" with witnesses above. Note: Sec. 6 (3-13) above should be Section 1 (3-13) and 30" stump is believed to be original witness from Ed Strong 1874 survey.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

A-02: West 1/4 post Section 6, T. 3 S., R. 12 W.; ratified by the Kalamazoo County Remonumentation Program Peer Group on May 16, 1996, and is accepted as the best available evidence of the position of the corner. This position not established by original Government Surveyors. Found stone with "x" and assumed witness from 1874 survey by Ed Strong. Removed stone and placed 30" Harrison Monument in its place.

PK Nail in East side	8" W. Cherry	N. 15° E.	13.64'
Nail in South side	30" Stump (Oak)	West	1.30'
Nail in Southwest side	13" Sassafras	S. 58° E.	71.00'
Nail in Southwest side	Twin 16" Oak	S. 30° E.	54.28'

Signed by

Robert E. Snell

Date

10-14-96

Surveyor's Michigan License No.

9734