

SURVEY &  
REMONUMENTATION

LIBER

1 PG 1157

APR 27 1995

COMMISSION

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Kalamazoo

(County)

Texas Township

Located In:

Corner Code #

1. Public Land Survey

T 3S R 12W

E-2

2. Property Controlling  
in Section

S T R

3. Miscellaneous  
Property in Sec.

S T R

4. Lot No. , Recorded Plat

5. Private Claims

Thomas W.

Chettleburgh

March 22

1994

I, Thomas W. Chettleburgh, in a field survey on March 22, 1994, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

Corner Post set by U.S. Government Deputy Surveyor Thom Whelpley, 1929.

Accessories: S7 1/2°E Bl. Oak 9" .18, S78°W Bl. Oak 9" .87

Ed Strong, 1913, Found 2 stones 3' below, set iron 3' long

Kalamazoo Witness Sheets, Stake with stones

MDOT, 1962, Found stake with stones, set iron at surface

W. Monch, 1966, 1" boat spike.

D. Erickson, 1992, Found 3/4" iron pin in centerline N-S road, Recorded LCRC, Liber 1, Page 975.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Original corner post & accessories not recovered.

Found 1" boat spike over center of 2 stones 2.8' deep in centerline N-S road, checks corner location as described and recorded by D. Erickson.

The 1" boat spike over center of 2 stones was accepted as a careful and faithful perpetuation of the position of the original corner and was ratified by the Kalamazoo County Remonumentation Program Peer Group on April 21, 1994.

Replaced 1" boat spike with 20" Harrison Monument and Monument Box.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

20" Harrison Monument in monument box.

Spike SW side Power Pole

S20°E

70.06'

NE side 2" steel fence post, N. end fence,

S56°W

59.10'

Spike S. side Power Pole

S77°W

84.61'

Spike S. side 8" W. Pine

N83°W

44.57'

Spike NE side 12" W. Pine

N22°W

72.03'

RATIFIED  
BY KALAMAZOO COUNTY  
REMONUMENTATION  
PEER GROUP

4-21-94



Signed by Thomas W. Chettleburgh Date July 5, 1994

Surveyor's Michigan License No. 16036