



LC-000047

Page: 1 of 1

10/28/1999 03:11P
BK-2 Pg-500LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Kalamazoo (County)	Located In:	Corner Code#
Wakeshma Twp.		
1. Public Land Survey	T 4S R 9W	A5
	T R	
	T R	
	T R	
	T R	
2. Property Controlling in Section	S T R	
	S T R	
3. Miscellaneous Property in Sec.	S T R	
	S T R	

SURVEY &
REMONUMENTATION

FEB 08 2000

SECTION

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

I, Gary D. Hahn, in a field survey on August 5, 1999
do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner
points mentioned in lines 1 and 2 above were in conformance with regulations and rules
therefore as required in the current manual of survey instructions of the United States
Department of the Interior, Bureau of Land Management or by a decree of a Court of Law
and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance
with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law;
established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

1826 - Corner established by U.S. Deputy Surveyor Robert Clark, Jr.: "Intersected W. boundary 161
lks. S. of post. Set post at int. cor. to sec. 7 + 18. Elm 20 in. N 23° E 38 lks.
Wh. Ash 8 in. S 16° E 9 lks."

1885 - F. Hodgman: "Found old stake 161 lks. South of Brady Corner. Set marked stone w/crockery over".

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Original monument and accessories not recovered. Found a 1/4" diameter 8" long rod and a 2" diameter 3" long pipe in an asphalt road. Removed.
Found a 1/4" diameter 20" long rod at a depth of 2.5 feet below the road surface. Rod was 1.28 feet North and 0.24 feet West of the surface rod.
Removed. Found a 15" x 16" x 10" deep flat stone w/crockery along it's North side at a depth of 40" below the road. No marks on the stone were
found. Center of the stone was 1.13 feet North and 0.22 feet East of the surface rod.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

A5, Northwest Corner of Section 18, Town 4 South, Range 9 West. Ratified by the Kalamazoo County Remonumentation Peer Group on September
23, 1999. The position of the found stone is accepted as the best available evidence of the position of the original corner. Set a 20" Harrison
Monument in a monument box 1.17 feet North and 0.10 feet East of the former surface rod. This position places the Harrison Monument at the
government jog distance of 106.26 feet South of the Brady Township corner M5.

Witness Ties: Found nail w/tab in 12" Maple N 88° E 55.14'
Found PK nail in 15" Maple S 46° W 43.08'
Set 1/2" rebar flush w/curb N 58° E 27.13'
Set 1/2" rebar flush w/curb N 40° W 29.43'

RATIFIED
BY KALAMAZOO COUNTY
REMONUMENTATION
PEER GROUP
9-23-1999Signed by _____
Surveyor's Michigan License No. 38116

Date 10/18/99

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS,
JAN. 28, 1971REVISED MAY 14, 1975
REVISED JAN., 1983 REVISED OCT., 1995