SURVEY & REMONUMENTATION

FEB 2 6 1998

FEB 2 0 1330	Oner	054
SECTION SECTION Wakeshma Township For corners in Wakeshma Township	LIBER 2PAGE	STATE OF COUNTY OF RECEIVED 17
Kalamazoo Located In: Corner Code #	CLERK	17 OF 17 OF 17 OF 17 OF
1. Public Land Survey T 4S R 9W E-10 T R T R	- REGISTE	F MICHICAN F KALAMAZOO TOR RECORD 7 AM 9 30
2. Property Controlling S TR	Register of Deeds St	
4. Lot No, Recorded Plat1 5. Private Claims2	A B C D E F C	3 H I J K L M
I. Robert F. Snell in a field survey on August 11 1997 do hereby state that under requirements of P.A. 74. Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, recovered, found as expressed below:	19 20 21	15 14 13
NOTE: Not more than 2 comers, all in the same town and range, may be recorded //	0 30 29 28	27 26 -25
BY KALAMAZOO COUNTY 1	2 31 32 33	34 35 36
REMONUMENTATION PEER GROUP 4-(8-(497) A. Description of original monument and accessories and/or subsequent restoration:	3	
Section Post		
Pooch 30" South 10 1ks.		
Beech 8" N. 440 E., 19 lks. 1872: Samuel Hodgman, Deputy County Surveyor: "Found stake and set stone with "+" and marked:	verified by tra	ce of witnesses
Sugar 14" N. 78½° W. 46 lks. Beech 10" S. 63½° W. 42½ lks.		
DCCCII	r v 12"\ with '	'+" on top, bent
1968: Wilkins & Wheaton Engineering Co.: Found Stone (1 x 1	X 12 / H. O.	100 701
14" Spruce N660-45'-W, 52.60', NE corner 12" Red Cedar S500-53'-W, 51.5', 18" Maple	N420-48'-E Pole S890-0	4'-E., 23.8'
1997: Found stone (1' x 1' x 2') with "+" down about 9" with spruce, NE corner of house (now different), 18" Maple a as 1872 witness Beech 10" now 50".	manumant hay a	ver mn.cu 14
C. Description of monument for comer and accessories established to perpetuate locating the post E-10: West ½ Post, Section 28, T. 4 S., R. 9 W., ratified by Remonumentation Program Peer Group on September 18, 19 and faithful perpetuation of the original corner. Fou "+" as set in 1872 by S. Hodgman, Deputy County Survey stone and placed 20" Harrison monument over stone and lid) over monument.	97 and is accept nd stone (1' x or and reset in placed monument	1' x 2') with n 1968. Lowered t box (without
P.K. nail in West side 12" Cherry N. P.K. nail in South side 12" Manle N.	880 E. 23. 22 ⁰ W. 48. 740 W. 28.	06' 70' 06'
Signed by John Date	12-16-9	<u>Z</u>
Surveyor's Michigan License No. 9734		