

## LAND CORNER RECORDATION CERTIFICATE

| For corners in   | 1970  |
|--|---|
| Kalamazoo Located In: Corner Code#  (County)  Wakeshma Township  | SURVEY & REMONUMENTATION                      |
| 1. Public Land Survey  | FEB ( 8 2000                                  |
| T  | SECTION  Register of Deeds Stamp & File Numbe |
| 4. Lot No, Recorded Plat   | A B C D E F G H I J K L                       |
| I, Gary D. Hahn , in a field survey on October 29 , 19 98 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules   | 3   |
| therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; | 6 18 17 16 15 14 13 7 8 19 20 21 22 23 24     |
| established, re-established, monumented, recovered, found as expressed below:  | 9 29 28 27 26 25                              |

- A. Description of original monument and accessories and/or subsequent restoration:
- 1826 Corner established by U.S. Deputy Surveyor, Robert Clark, Jr. Beech 13 in, S 78 ° W 12 lks. Beech 5 in. N 261/2 ° E 10 lks.
- 1872 Samuel Hodgeman: "Stone with drill hole + side stones N+S 50 lks,"

KCRC Witness Tie Book:

on this certificate.

(W) Map. 24" N 2 ° W 29.05' (W) Map. 16" N 35 ° W 35.55' (W) Map. 20" S 15 ° E 26.65' (W) Stone set 33' North + South. (W) Drilled stone by an (H)

NE. Cor. Hse. 52.25' NW. Cor. Hse. 70.06

RATIFIED BY KALAMAZOO COUN REMONUMENTATION PEER GROUP 12-17-1998

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Original monument and accessories not recovered. No surface monument found. Excavated a 7' (N+S) x 17' (E+W) x 7' deep hole centered on the bisection of a line between corners E7 and G7. Found no evidence of stone w/drill hole. Area may have been excavated for road. Side stone to the north gone due to fiber optic installation. Side stone to the south gone due to driveway cut.

- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
- F7, South Quarter Post of Section 16, Town 4 South, Range 9 West. Ratified by the Kalamazoo County Remonumentation Peer Group on December 17, 1998. The position of the bisection of the line between corners E7 and G7 is accepted as a careful and faithful reestablishment of the position of the original corner. Set a 30" Harrison Monument in a mon. box at said bisection.

Witness Ties:

Set Mag Nail in NE. side P.P. S 50 ° E 41.90 SW corner of house foundation N 40 ° W 69.43'

Found 4" x 8" flat stone 1 - 2 inches below sod North 31.97'

Set Mag Nail in NW face 15" Pine S 60 ° W 65,33"

LAND SURVINGE OF THE PROPERTY OF THE PROPERTY

Signed by Surveyor's Michigan License No 38116

Date 10/30/99

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS,