



LC-000040  
Page: 1 of 1  
10/28/1999 03:11P  
Bk-2 Pg-493

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Kalamazoo

(County)

Located In:

Corner Code#

Brady Twp.

1. Public Land Survey

T.4S R.10W

M2

T. R.

T. R.

T. R.

T. R.

2. Property Controlling  
in Section

S.

T. R.

S.

T. R.

3. Miscellaneous  
Property in Sec.

S.

T. R.

S.

T. R.

SURVEY &  
REMONUMENTATION

FEB 08 2000

SECTION

Register of Deeds Stamp & File Number

4. Lot No. , Recorded Plat

5. Private Claims

I, Gary D. Hahn, in a field survey on August 10, 1999

do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

1826 - Corner established by U.S. Deputy Surveyor Robert Clark, Jr.: "Set quarter section post W. Oak 10 S 21½° W 58 L. Wh. Oak 8 N 64° W 78 L."

1958 - K.C.R.C. plans call for an iron at the East Quarter post of Section 1.

1976 - L.C.R.C. L.1, P. 647 Don Gilchrist: "Found ½" iron in mon. box" Twin 12" Walnut S 70° W 32.10' Fence post N 45° E 46.90' Fence post S 50° E 45.15' 4.5' N of fence to West

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Original monument and accessories not recovered. Found a ½" diameter 18" long rod in a monument box in the centerline of 36<sup>th</sup> Street. Excavated a 6' (East & West) x 8' (North and South) x 6½' deep hole through sand and into 3' of natural clayey sandy soil. Found no other corner evidence.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

M2, East Quarter Post Section 1, Town 4 South, Range 10 West. Ratified by the Kalamazoo County Remonumentation Peer Group on September 23, 1999. The position of the found ½" rod is accepted as the best available evidence to the position of the original corner. Placed a 20" Harrison Monument in a monument box in place of the ½" found rod.

Witness Ties:

Found Harrison Monument in monument box South 104.64 feet (Wakeshma Corner A2)

Set PK nail in 15" Walnut S 75° W 32.00'

Set ½" iron in front of a concrete wall N 70° E 20.48'

Set ½" iron in front of the South concrete wall S 45° E 25.42'

Set PK nail in 8" Pine N 35° W 56.10'

RATIFIED  
BY KALAMAZOO COUNTY  
REMONUMENTATION  
PEER GROUP  
9-23-1999



Signed by [Signature]  
Surveyor's Michigan License No. 38116

Date 10/18/99

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS,

JAN. 28, 1971

REVISED MAY 14, 1975

REVISED JAN., 1983 REVISED OCT., 1995