

SURVEY & REMONUMENTATION

AUG 22 1995

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

STATE OF MICHIGAN
COUNTY OF KALAMAZOO
RECEIVED FOR RECORD
95 APR 26 AM 11 09

For corners in **COMMISSION**

Kalamazoo
(County)
Schoolcraft Township

1. Public Land Survey Located In: Corner Code #
T 4 S R 11 W C-13
T R
T R
T R

2. Property Controlling S T R
in Section S T R

3. Miscellaneous S T R
Property in Sec. S T R

4. Lot No. , Recorded Plat
5. Private Claims

James J. Jones
CLERK-REGISTER

LIBER 1 1297

Register of Deeds Stamp & File Number

I, Robert E. Snell, in a field survey on December 8, 19 94, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and/or subsequent restoration:

1825: U.S. Government Survey; Set Post, Corner to Sections 31 and 32.

Aspen 12" North 49° East 442 Lks
W. Oak 14" North 08° East 468 Lks

1889: F. Hodgman, County Surveyor; Set Post on South side of fence in angle of ditch, South 08° West, 468 Lks from U.S. Bearing Tree now standing.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

1994; Found 3" round clay tile by Malstrom and Associates from information supplied by Gove Associates.

Found tile on East side of 4" pipe, no witnesses.

RATIFIED
BY KALAMAZOO COUNTY
REMONUMENTATION
PEER GROUP
12-15-94

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

C-13 Southwest Corner Section 32, T. 4 S., R. 11 W., Ratified by the Kalamazoo County Remonumentation Program Peer Group on December 15, 1994. Found 3" clay tile as set by F. Hodgman in 1889 remonumentation survey and is accepted as a careful and faithful perpetuation of the position of the original corner. Placed a remonumentation sleeve over tile.

Center Line	4" Steel Post	North 30° West	0.45'	
PK Nail in South Side	10" Elm	North 40° West	7.30'	
PK Nail in South Side	8" Elm	South 05° West	40.22'	NOTE: All trees
PK Nail in Southwest Side	8" Maple	North 10° East	37.78'	triple blazed
PK Nail in South Side	8" Maple	West	30.70'	

Signed by Robert E. Snell Date 4-26-95
Surveyor's Michigan License No. 9734