

FEB 18 1994

LIBER

1 PG 1001

COMMISSION

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

<u>Kalamazoo</u>		Located In:	Corner Code #
(County)			
SCHOOLCRAFT TOWNSHIP			
1. Public Land Survey	T <u>4S</u> R <u>11W</u>		<u>G-7</u>
	T _____ R _____		
	T _____ R _____		
	T _____ R _____		
2. Property Controlling	S _____ T _____ R _____		
In Section	S _____ T _____ R _____		
3. Miscellaneous	S _____ T _____ R _____		
Property in Sec.	S _____ T _____ R _____		
4. Lot No. _____, Recorded Plat _____			
5. Private Claims _____			

STATE OF MICHIGAN  
COUNTY OF KALAMAZOO  
RECEIVED FOR RECORD  
93 OCT 25 AM 9 38  
CLERK-REGISTER  
Register of Deeds Stamp & File Number

I, John G. Kester, in a field survey on July 30, 19 93, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

**NOTE:** Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

Corner Post established by U.S. Government Deputy Surveyor Robert Clark, 1826, Post in Mound in Prairie no accessories. Resurvey by F. Hodgeman, 1889, Found Marked Stone of old survey. Set Post (Solid Clay Tile with "X" on top), Accessories: Cherry 2" N44W 66 & 2/3 Lks, Locust 12" S56 1/4 E 54 Lks.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Original Corner not recovered.  
Found R.R. Spike in Asphalt Surface. Found Solid Clay Tile with "X" on top (2.81' East and 1.60' South of R.R. Spike) as called for in 1889 resurvey by F. Hodgeman. All Accessories gone.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

G-7, Section Corner 15, 16, 21 & 22, T4S - R11W, Ratified by Kalamazoo County Remonumentation Program Peer Group on August 19, 1993. Found Solid Clay Tile with "X" on top called for in 1889 resurvey and is accepted as a careful and faithful perpetuation of the position of the original Corner. Removed R.R. Spike possibly used as Corner. Placed 30" Harrison Monument above Tile and placed Monument Box over Corner.

N.W. Corner House Foundation S 40 E 94.36'  
Set P.K. Nail in P.P. S 30 W 49.66'  
Set P.K. Nail in P.P. N 67 W 88.44'  
S.E. Corner House Foundation N 30 W 75.85'

Signed by John G. Kester  
Surveyor's Michigan License No. 16046  
Kalamazoo County Road Commission

Date 10-20-93

**RATIFIED**  
**BY KALAMAZOO COUNTY**  
**REMONUMENTATION**  
**PEER GROUP**  
8-19-93