

FEB 08 1999

LIBER

2PAGE 387

## SECTION LAND CORNER RECORDATION CERTIFICATE

PRAIRIE RONDE TWP **Filing Requirement of Act 74, Mich. P.A. 1970**

For corners in PRAIRIE R  
KALAMAZOO  
(County)

Located In:

Corner Code #

		4S.		12W.		J-3	
1. Public Land Survey		T		R			
		T		R			
		T		R			
		T		R			
2. Property Controlling in Section	S	T		R			
	S	T		R			
3. Miscellaneous Property in Section	S	T		R			
	S	T		R			

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_

5. Private Claims \_\_\_\_\_

6. IWM Job No. 30465

I, Allen H. McMachen, in a field survey on September 29, 1997

do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Professional Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

**NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.**

**A. Description of original monument and accessories and/or subsequent restoration:**

1829 - E.H. Lytle, D.S., Set quarter Section post, Lynn 18" South 10 lks., Ash 20" N.  $33\frac{3}{4}^{\circ}$  E. 36 lks..

1980 - Ingersoll, Watson & McMachen, Inc., Obtained signed affidavit from Lyle Williams (owner of adjacent property) stating that he and his father in ±1925 set pipe fence corner in concrete 6" South and 6" West of the South quarter corner, Sec. 2. Survey crew placed "PK" Nail with plastic cap as instructed by Mr. Williams. 2" Pipe in concrete S. 45° W. 0.70', 6" Ash N. 05° W. 27.90', Triple 12" Cherry N. 45° W. 16.30'.

**B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:**

Found "PK" nail and plastic cap in concrete 6" North and 6" East of metal fence post per 1980 information. Measured West 2666.53 feet to standard marker at S.W. corner. Measured North 2662.04 feet to standard marker at Center quarter corner.

**RATIFIED**  
**BY KALAMAZOO COUNTY**  
**REMONUMENTATION**  
**PEER GROUP**  
12-18-1997

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Found "PK" nail and plastic cap is accepted as the best available evidence of the position of the original corner. Chipped out concrete around nail and placed the cap only from a Harrison Monument in hole and cemented in place, Accessories:

Nail & Tab in SE side of 12" Mulberry N. 25° E. 63.00'

Nail & Tab in SW side of 10" Multi-stemmed maple S. 80° E. 11.02'

Nail & Tab in North side of 10" Multi-stemmed maple West 40.04'

Metal fence post S. 45° W. 0.70'

29.7' South of centerline "U" Avenue

Signed by W. H. M. F. Acker Date 2/15/98

Surveyor's Michigan License No. 16935

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971

REVISED MAY 14, 1975  
REVISED JAN., 1983

