

**LAND CORNER RECORDATION CERTIFICATE**  
**FILING REQUIREMENT OF ACT 74, MICH. P.A.1970**

FOR CORNERS OF--:	LOCATED IN--:	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY _____	T. 18 N. R. 12 W.	J-3; K-2; L-6; M-6
2. PROPERTY CONTROLLING IN SECTION _____	T. _____ N. S. R. _____ E. W.	
3. MISCELLANEOUS PROPERTY IN SECTION _____	T. _____ N. S. R. _____ E. W.	
4. LOT NO. _____, RECORDED PLAT _____		
5. PRIVATE CLAIMS _____		

REGISTER OF DEEDS STAMP AND  
FILING NUMBER

I, Carl F. Roser, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on April 30, 1975, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on \_\_\_\_\_, 19\_\_\_\_, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

~~A. Description of original monument and accessories and/or subsequent restoration:~~

C. (continued)

M-6

Found iron & added DNR mon. (buried)  
12" Oak S60°W 56.3  
5" Oak N53°W 70.4  
SW corner of power line tower #3967  
N75°E 38.5  
Set cedar post w/loc. tag  
Due W 33

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

- J-3 Reestablished corner per standard B.L.M. instructions.  
K-2 Reestablished corner per standard B.L.M. instruction; single proportionate to U.S.  
L-6 Established center of Section 13 at intersection of quarter lines.  
M-6 Found Geo. Johnson iron in approximate center of N-S county road (sand).

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

J-3	K-2	L-6
Set DNR mon. & cedar post	Set DNR mon. & cedar post	Set 1"x3' Pipe & cedar post
13" W. Oak N40°E 10.5	5" W. Oak N33°W 13.4	w/loc. tag
6" B. Oak S30°E 15.9	14" Oak S70°E 26.7	16" W. Pine S40°E 92.4
5" R. Oak S42°W 26.2	9" W. Oak S07°E 16.1	3" W. Pine N57°E 34.2
		One-strand E-W fence
		Due S 108

SIGNED BY Carl F. Roser 9-4-75 DATE \_\_\_\_\_

SURVEYOR'S MICHIGAN REGISTRATION NO. 12028

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY \_\_\_\_\_ DATE \_\_\_\_\_

CHIEF OF SURVEY PARTY

APPROVED AND SIGNED BY \_\_\_\_\_ DATE \_\_\_\_\_

MICHIGAN REGISTERED LAND SURVEYOR

(SEAL)

CHERRY VALLEY TOWNSHIP  
LAKE COUNTY

SURVEYOR'S MICHIGAN REGISTRATION NO. \_\_\_\_\_