

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970

For Corners In:
Lake
(County)

Located In

Corner Code #



RECEIVED
05/05/2014 3:55:21 PM
LAKE COUNTY, MICHIGAN
SHELLY MYERS, CLERK/REGISTER/CFO

RECORDED
05/05/2014 3:56:18 PM
LAKE COUNTY, MI
SHELLY MYERS, REGISTER OF DEEDS
RECEIPT# 5785, STATION 1
\$14.00 LAND CORNER



Liber C8

Page 6

Register of Deeds Stamp & File Number

1. Public Land Survey T _____ R _____
T _____ R _____
2. Property Controlling in Section S 4 T 19N R 11W 5
S _____ T _____ R _____
3. Miscellaneous Property in Section S _____ T _____ R _____
S _____ T _____ R _____

4. Lot No: _____ Recorded Plat: _____

5. Private Claims: _____

I, Joshua R. Davidson, in a field survey on April 9, 2014 do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6			5		4			3		2		1
3													
4	7			8		9			10		11		12
5													
6	18			17		16			15		14		13
7													
8	19			20		21			22		23		24
9													
10	30			29		28			27		26		25
11													
12	31			32		33			34		35		36
13													

A. Description of original monument and accessories and/or subsequent restoration:

5 – CN 1/6 corner section 4, T19N, R11W

– 1982 – LCRC L.3, P.20 – C. Roser, PS #12028 –
Etab N 1/8 cor on N-S 1/4 line, sec 4 per std BLM
instruction (pro-rated to GLO Plat). – Set 5/8" X 34"
rerod W/rls cap & cedar post W/loc tag. – 11"
Cherry S40°W 58.4'; 1" R Pine S45°W 47.4'.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

5 – CN corner section 4, T19N, R11W

Found 5/8" rebar & cap #12028. Did not use this
position as it is based on the rejected positions of F1 &
F3. Set a stamped 2" aluminum cap on 5/8" X 34"
rebar per standard BLM procedure.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

5 – a stamped 2" Aluminum Cap on 5/8" X 34" rebar.

N23°E 38.97' to set nail & tag in E. side 6" W. Pine
N88°E 57.93' to set nail & tag in S. side 5" W. Pine
S65°W 72.82' to set nail & tag in SE. side 12" W. Pine
N87°22'W 32.24' to found 5/8" rebar & cap #12028

Set blue post with location tag 1' East.

Signed by:

Joshua R. Davidson

Date:

MAY 5, 2014

Surveyor's Michigan License No.:

46659

