


STATE OF MICHIGAN  
DEPARTMENT  
OF  
NATURAL RESOURCES  
LAND CORNER RECORD

LEECLAUCAU COUNTY

T 28 N R 12 & 13 W

DESCRIPTION OF CORNER Sec corner common to Sections 25-30 36-31  
CORNER MONUMENT Found high shoe at corner fence post (Fence S & E) Added  
Std. Dept. Mon. with Cedar Guard Post.  
DATE MONUMENT PLACED AND WITNESSED 7-1-69  
WITNESSES TO CORNER.....



9" Elm S 76 W 3.6'

5" Maple S 44 E 8.8'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

**This corner was recovered during a retracement of boundary survey in this area.  
Data on the corner was obtained from P. J. O'Hon, County Surveyor.**

SURVEYOR'S SEAL

SIGNED

*Carl F. Roer*

DATE

8-8-69

DISTRIBUTION:

REGISTERED LAND SURVEYOR **12028**

County Courthouse  
Area Forester (Regions I & II)  
District or Region Surveyor  
Forestry Div., Lansing

R 4047  
Rev. 10/68