

**For corners in
Leelanau**

Corner Code ~~##~~

- | | | | | | | |
|---------------------------------------|---|------------|---|------------|-------------|------------|
| 1. Public Land Survey | T | <u>28N</u> | R | <u>13W</u> | <u>I-10</u> | |
| | T | <u>28N</u> | R | <u>13W</u> | <u>J-10</u> | |
| | T | <u>28N</u> | R | <u>13W</u> | <u>K-10</u> | |
| | T | _____ | R | _____ | _____ | |
| 2. Property Controlling in Section | S | <u>26</u> | T | <u>28N</u> | R | <u>13W</u> |
| | S | _____ | T | _____ | R | _____ |
| 3. Miscellaneous Property in Sec. | S | _____ | T | _____ | R | _____ |
| | S | _____ | T | _____ | R | _____ |

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

[illegible]

I, Carl F. Roser, in a field survey on April 30, 1987, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

C. Continued:

AXI PRGHI PRXI PUHOKUONUNOTWACCHSCHI XHOHXSOPXCOLPUJSTOIKOX

| K-10 | | | 15 | | |
|----------------------------------|-------|--------|--|-------|---------|
| Fd Dept mon, raised w/ 5/8" x 9" | | | Fd 3/8" x 1 3/4" strap iron raised w/ 3/8" spike | | |
| rerod w/RLS cap | | | | | |
| *10" Ironwood | N54°W | 62.40' | 12" Twin Maple | N46°W | 118.82' |
| * 5" Ironwood | N86°W | 54.88' | NE cor of house | S14°W | 82.23' |
| * Sq.cedar post | S88°E | 32.84' | 7" White Pine | S20°E | 83.05' |
| 26" Beech | N80°W | 73.5' | | | |
| 17" Ash | S25°E | 118.7' | | | |

*= Wit by MDOT (1984) per DNR survey

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

I-10 - Fd. R.R. spike in ctr. of N-S B. top road, in line with berm & tree row to west & 1' north of fn. to east (1983).

J-10 - Fd. old corner fn. post hole (w/conc poured around it) with old fns. N-S-E-W in 1983. M.D.O.T. drove 3/4" x 40" pipe inside same in 1984.

K-10 - Department corner as established by single proportion in D.N.R. 1969 survey (Project 68-34).

15 - Found 3/8" iron for the SW corner of SE $\frac{1}{4}$ -SW $\frac{1}{4}$ of Section 26. Corner is in center E-W B. top, M-72.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

| I-10 | | | J-10 | | |
|-------------------------------------|-------|--------|-------------------|-------|--------|
| Found R.R. spike in ctr. N-S B. top | | | * 3/4" x 40" pipe | | |
| *6" Red Pine | N74°E | 44.88' | *20" Twin Cherry | S35°E | 12.81' |
| *6" White Pine | N48°E | 65.46' | *24" Cherry | N60°E | 8.45' |
| *5" Red Pine | N36°E | 74.08' | * 8" Red Pine | N40°W | 26.75' |
| *Sawed-off T.P. | | | * 2" Maple | N02°E | 21.74' |
| 1' high | S66°E | 47.05' | | | |

*= MDOT 1984 wits per DNR survey

*= Cor Set & Wit by MDOT (1984) per DNR sur.

Signed by Carl F. Novak 0-17-87 Date

Survivor's Michigan License No. 12028

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYING JAN-70

