1993

COMMISSION

LAND CORNER RECORDATION CERTIFICATE

		•	. •
C TATE	ጣሮ	MICLICAL	
SIMIL	ML.	MICHIGAN	•
COLINITY	0	Tri Lais	
	UΓ	LEELANA	i II
DECENT	'n.	-05 00 00	2.2
REDEIVE	()	OR RECOI	411

- 12 Jun

1993 DEC 28 PM 4: 24

_		Filin	g Requirem	ent of Act 74, Mi	ch. P.A. 1970	1			V 20	1 11	٦٠ ٤	. 7	
For	corners in						,	0		1	,.		
	icelanau	Located In	:	Corner Code #			3		Lara TER O	- , ,		:	
1.	Public Land Survey	T 29N (T)	R ·	I-\$					FILE ER 2				
3.	Property Controlling in Section Miscellaneous Property in Sec.	S T I S T I S T I	R · · · · · · · · · · · · · · · ·			gister	of D		Stamp			ber	
5. do h in lin curr Man abov	Bteven P. Bye ereby certify that under re nes 1 and 2 above were i ent manual of survey instragement or by a decree of we were in conformance wirt of Law; established,	, in a field survey on quirements of P.A. 74, Min conformance with regrections of the United StacCourt of Law and/or the the rules of the Michigan	December chigan P.A. of the ulations and in ates Department at the corner progan Board of Li	29, 19 1970, the corner points ules therefore as requ ent of the Interior, Bure oints mentioned in line and Surveyors or by a	93 mentioned uired in the eau of Land es 3, 4 and 5 Decree of a	2 3 4 5 6 7 8	- 18	C D	9	G H	11 14 23	K	12 13
ехрі	ressed below: FE: Not more than 4 con this certificate.	corners, all in the sam	• •		•	10	30-	29 	33	34	35		36
A.	Description of original	monument and acces	sories and/o	r subsequent resto	ration:						.,	-	
]	-1: NE corner,	Section 3:	Hemlock	st corner to s 10 - S 50 W, - S 74 E, 43	32 links	& 3 '	•						
S C I	County Surveyor r Stone with "X" 1 of North side of Couble 13" Black South tree of tri	'West of end of red granite sto cherry - N 68 1	one 18" x E, 10'	15" on top.	ite stone 3	3' x	4"	x 1.	5',,'	4 No	orth		٠
В.	Description of corner e	evidence found and/or	r method app	olied in restoring or	reestablishing	corn	er:						
]	-1: NE corner,	Section 3:	stone, (/2" iron rod w 0.40' North of anite stone	ith cap #2 red grani	:842(:te s	0.	10' 1 e, 1	East .00'	of r West	ed g . of	gran blu	ite e-

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

I-1: NE corner, Section 3:

1/2" iron rod with cap #28420 accepted by the Leelanau County Remonumentation Peer Group, November 29, 1993, and replaced with a 3/4" i.d. galvanized iron the shalong with a brass cap.

West end of blue gray granite stone - East 1.00' North side of red granite stone - South 0.40' 18" double cherry - N 68 E, 24.55' 1/2" iron rod w/cap #28417, #30079 - East 114.39' Power pole - N 25 E, 217.21'

21' North of centerline of Lavassar Rd.

Signed by	ven P. Bye	
Surveyor's Michigan Li		

12-21-93

_ Date _

LAND

STEVEN P BYE LAND SURVEYOR No.

REVISED JAN., 1983