

MAR 04 1999

SECTION

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Leelanau Located In: Corner Code #  
(County)

1. Public Land Survey T32NR11W E-10  
T R  
T R  
T R  
T R

2. Property Controlling S T R  
in Section S T R

3. Miscellaneous S T R  
Property in Sec. S T R

Barbara Kirt 12/31/98  
Leelanau Reg of Deeds 9:56 am  
BJK Fee: 9.00  
04B00002 P0294 Page 1 of 1

#597

Register of Deeds Stamp & File Number

4. Lot No. , Recorded Plat  
5. Private Claims

I, David T. Rowe, in a field survey on 11-30, 1998 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

|    | A | B  | C | D  | E | F  | G | H  | I | J  | K | L  | M |
|----|---|----|---|----|---|----|---|----|---|----|---|----|---|
| 1  |   |    |   |    |   |    |   |    |   |    |   |    |   |
| 2  |   | 6  |   | 5  |   | 4  |   | 3  |   | 2  |   | 1  |   |
| 3  |   |    |   |    |   |    |   |    |   |    |   |    |   |
| 4  |   | 7  |   | 8  |   | 9  |   | 10 |   | 11 |   | 12 |   |
| 5  |   |    |   |    |   |    |   |    |   |    |   |    |   |
| 6  |   | 18 |   | 17 |   | 16 |   | 15 |   | 14 |   | 13 |   |
| 7  |   |    |   |    |   |    |   |    |   |    |   |    |   |
| 8  |   | 19 |   | 20 |   | 21 |   | 22 |   | 23 |   | 24 |   |
| 9  |   |    |   |    |   |    |   |    |   |    |   |    |   |
| 10 |   | 30 |   | 29 |   | 28 |   | 27 |   | 26 |   | 25 |   |
| 11 |   |    |   |    |   |    |   |    |   |    |   |    |   |
| 12 |   | 31 |   | 32 |   | 33 |   | 34 |   | 35 |   | 36 |   |
| 13 |   |    |   |    |   |    |   |    |   |    |   |    |   |

A. Description of original monument and accessories and/or subsequent restoration:

E-10 1/4 Corner common to Sections 28 and 29:

G.L.O. Notes: 1855 Reestablished Old Corner - 14" Sugar N34°W 19 lks., 10" Birch S55°W 35 lk  
County Records: 1930's H. Brehmer - Fd. Stone - 8" Box Elder N09°30'W 45.9', 5" Maple S84°05  
35.8', 10" Maple S05°30'W 56.3' measured along ground.

17" x 16" x 12" Deep White Granite With "X" On Top Found - 1987 N. 0'Non

Stone With "X" Found - 1989 N. 0'Non

Stone With "X" Found - 1990 N. 0'Non

(Section A. continued below)

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

E-10 1/4 Corner common to Sections 28 and 29:

Found 17" x 16" x 12" Granite Stone With "X" On Top 0.4' S. Found Capped Iron P.S. # 28420.

(Section A. continued)

Rock With "X" Found - 1991 G. Stowe

Stone With Cross Found - 1992 N. 0'Non

Stone With Cross Found - 1993 N. 0'Non

APPROVED LAND CORNER

P.A. 345 OF 1990

LEELANAU COUNTY

DATE: 12-8-98

COUNTY REP. W.M. O'Non

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

E-10 1/4 Corner common to Sections 28 and 29:

17" x 16" x 12" Granite Stone accepted as a careful and faithful perpetuation of the position of the original corner by the Leelanau County Peer Group, 12-08,1998 and replaced with 3/4" i.d. galvanized 36" long Iron Pipe with a brass cap.

Witnesses: N02°W 46.20' - Found Nail in W. Face 14" Ash

West 34.36' - Set Nail 6.0' Above Ground in N. Face Blazed 12" Maple

S12°W 56.21' - Set Nail 5.5' Above Ground in W. Face Blazed 12" Maple

S22°E 48.68' - Found Spike in W. Face Blazed 10" Ash

Signed by David T. Rowe

Date Dec 29, 1998

Surveyor's Michigan License No. 11192

