

MAY 18 1997

COMM. 1997

Filed Under Remonumentation Act 345 of 1990  
LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

LIBER 001 PAGE 127

For corners in

Lenawee  
(County)

Located In:

Corner Code #

1. Public Land Survey T 5 - S R 1 - E J - 6  
T \_\_\_\_\_ R \_\_\_\_\_  
T \_\_\_\_\_ R \_\_\_\_\_  
T \_\_\_\_\_ R \_\_\_\_\_
2. Property Controlling S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_  
in Section S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_
3. Miscellaneous S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_  
Property in Sec. S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_
5. Private Claims \_\_\_\_\_

I, Glenn E. Richard, in a field survey on August 16 1996, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

Not set in the original Government survey  
1940 Road survey by Harold Clegg notes show boat spike  
1964 Plat of PAMAWA Subdivision shows center of Section as point of beginning  
March 1972 I found boat spike in pavement and recorded it in Liber 1, Page 355  
July 16, 1991, Dermeyer Estates (Condominium) is tied to this corner.  
June 1994 Found iron pipe 1.5 deep in monument box and took additional witnesses as the road was to be rebuilt

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

August 16, 1995 Set 3/4" X 3' iron pipe in new monument box set by Lenawee County Road Commission during paving. Drove original iron pipe down deeper with the 3' gas pipe

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

3/4" X 3' gas pipe capped G.E.R. 13040 in monument box and is accepted as the best available evidence of the position of the corner.  
Found nail in S. face of 14" Oak N 75 E 30.13  
Found nail in W. face of 18" Oak S 45 E 49.70  
S.E. corner of house foundation S 25 W 161.97  
Found iron pipe East 32.93  
Found iron pipe East 72.51  
Found re-rod West 35.72  
Found re-rod West 101.01

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

STATE OF MICHIGAN  
LENAWEE COUNTY  
FILED

13 NOV 96 9:05 A.M.

JEANETTE D. KNOX  
Register of Deeds Stamp & File Number

Ratified by Peer Group in accordance with P.A. 345 Co. Rep. Glenn E. Richard Date 7-16-96

Signed by Glenn E. Richard Date 10-11-96  
Glenn E. Richard

Surveyor's Michigan License No. 13040

