

JAN 2 5 2000

Filed under Remonumentation Act 345 of 1990  
**LAND CORNER RECORDATION CERTIFICATE**  
 Filing Requirement of Act 74, Mich. P.A. 1970

SECTION

LIBER 1 PAGE 343  
 STATE OF MICHIGAN  
 LENAWEE COUNTY  
 FILED

For corners in

Lenawee  
 (County)

Located In:

Corner Code #

1. Public Land Survey	T	5	S	R	2	E	B-11
	T			R			
	T			R			
	T			R			
2. Property Controlling in Section	S			R			
	S			R			
3. Miscellaneous Property in Sec	S			R			
	S			R			

29 SEP 1999 5:56:58 PM

VICTORIA J. DANIELS  
 REGISTER OF DEEDS

Register of Deeds Stamp &amp; File Number

4. Lot No. \_\_\_\_\_ Recorded Plat \_\_\_\_\_  
 5. Private Claims \_\_\_\_\_

I, Glenn E. Richard, in a field survey on July 19, 1999, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A B C D E F G H I J K L M

1													
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

A. Description of original monument and accessories and/or subsequent restoration:

G.L.O. 1824, Hervey Parke set 1/4 Sec. post Y. Oak 28 N 20 W 15 Y. Oak 24 S 55 E 20  
 Could not find any information on this corner in any of the old survey records.  
 1935 Walter Frazier surveyed Slee Road and made no mention of this corner.  
 1967 The corner was re-established by Gillespie & Associates  
 1972 Werner Sommer found re-bar and recorded it in Liber 2, Page 43  
 1990 & 1991 I found 1/2" rod  
 1995 Steve Young found iron rod  
 1999 Mike Bartolo found capped iron in monument box

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

July 19, 1999 I found 5/8" X 12" re-rod which was pointed on the bottom. Replaced it with 5/8" X 3' re-rod with Lenawee County Re-mon cap stamped P.S. 13040 and set a monument box.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

5/8" X 3' re-rod with Lenawee County Re-mon cap stamped P.S. 13040 in monument box and is accepted as the best available evidence of the position of the original corner.

SW corner of brick house N 15° W 226.50  
 SE corner of brick garage N 5° E 224.50  
 Fd nail & M. Bartolo brass tag in E.P. N 80° W 175.19  
 Fd. nail & M. Bartolo brass tag in 14" Walnut 86.23  
 Fd. re-rod S 15° E 84.51



Ratified by Peer Group in accordance with P.A. 345 Co. Rep. Glenn E. Richard Date September 14, 1999

Signed by Glenn E. Richard Date Sept. 24, 1999  
 Glenn E. Richard

Surveyor's Michigan License No. 13040

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971

REVISED MAY 14, 1975  
 REVISED JAN., 1983

ADAPTED FOR WORD PROCESSING MARCH, 1993