

SURVEY & REMONUMENTATION

NOV 07 1994

Filed under Remonumentation Act 345 of 1990
LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

LIBER 001 PAGE 34

COMMISSION

For corners in

Lenawee

(County)

Located In:

Corner Code #

- Public Land Survey T-6-S R-3-E 1-3
T R
T R
T R
- Property Controlling S T R
in Section S T R
- Miscellaneous S T R
Property in Sec. S T R

- Lot No. _____, Recorded Plat _____
- Private Claims _____

I, Glenn E. Richard, in a field survey on October 10 19 94, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

G.L.O. January 1824, John Mack set post Cor. Sec. 2, 3, 10 & 11, B. Oak 25 N 37 W 51, Hickory 20 S 45 E 40.
May 1838, Survey of Sec. 11 shown in Satterhwaite book but monuments are not described.
July 1948, during a survey for road reconstruction a stone was found and "set spike" 30" Elm N 40° E 46', Cor. fence post N 45° W 35' & S 45° W 37.5
Nov. 1971, K.L. Suydam "set steel rod by proportional measurement" (same witnesses as shown on L.C.R.C., L. 1, P. 233).
Nov. 1972, K.L. Suydam found 1/2" steel rod and recorded it in L. 1, P. 233, nail & washer in 26" W. Oak NE 47.22, nail & washer in Tel. pole NW 38.00, nail & washer in Tel. pole NE 47.22

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

October 10, 1994, Found iron pipe in monument box

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

3/4" X 4" iron pipe capped G.E.R., P.S. 13040 in monument box and is accepted as the best available evidence of the position of the original corner.
Fd. 60d spike & disc in 30" Oak N 45° E 48.65
DbI. hd. nail & disc in pole next to tel. ped. S 40° E 44.67
DbI. hd. nail & disc in Elec. pole S 30° W 65.10
Cut "X" on C.M.P. S 60° W 68.27
Cut "X" on C.M.P. N 65° W 67.71

FILED

OCT 28 1994

LENAWEE COUNTY
JEANETTE D. NOX
REGISTER OF DEEDS

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

Ratified by Peer Group in accordance with P.A. 345

Co. Rep.

Glenn E. Richard

Date October 13, 1994

Signed by

Glenn E. Richard

Date

Oct. 20, 1994

Glenn E. Richard

Surveyor's Michigan License No. 13040

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971

REVISED MAY 14, 1975
REVISED JAN., 1983
ADAPTED FOR WORD PROCESSING MARCH, 1993

