THE TOTAL

JAN 2 2 2001

## Filed under Remonumentation Act 345 of 1990

## LAND CORNER RECORDATION CERTIFICATE

RECTION

For corners in

Filing Requirement of Act 74, Mich. P.A. 1970

(County)		Located in:		Corner Code #					Si	LENAW	MICHI EE COUN ILED	gan Ity	
1. Public Land Survey		T <u>- 6 - S</u> R <u>- 3 - E</u> T R T R		<u>K-10</u>					111	EC 2004	8. 9:47 J. DAI	HELS	ELS
Property Controlling     in Section     Miscellaneous	S S	T R			Re	giste	er of D	eeds			le Nun		
Property in Sec		T R					ВС	DE	F	3 Н	IJħ	( L N	Л
					2 3	6	5	4	3	2	1		
						4	7	8	9	10	-11	12	
t, <u>Clenn E, Richard</u> , in a field survey on <u>November 11, 2000</u> , do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5				entioned	6	18	17	16	15	14	13		
				of Land	8 9	19	20	21	22	23	24		
above were in conformance with the rules of the Michigan Board Court of Law; established, re-established, monumented, re-extablished below:						10 11	30	29	28	27	26	25	
NOTE: Not more than on this certific		all in the sar	ne town an	nd range, may be recorded	d	12 13	31	32	33	34	35	36	]
A. Description of ori	ginal monu	ment and ac	cessories a	nd/or subsequent restorat	tion:								
1894± Map in Early 1900's 1927 Fred So certificate indi Wh. Oak N 70 1957 M.S.H.I 1970 I found 1974 I found dbl hd nail & c	n James Bl John L. Rid bll P.S. 109 cates that po W 23.3 D. 1 1/4" iron 1/4" iron p disc in 32"	lair's book sl chard's reco 30 surveyed he found a i 24" Wh. Oa on pipe 2' be pipe from M ipe and reco Oak N 65° V	hows the cord= Stone the Girls T monument k N 88° 49 elow fill und M.S.H.D. wi orded it in L W 22.83 dl	raining School in Section (type not given). 1/4 P.	s survey ons 25 ar . 16" Wh e 26" Oá /4" X 4' i d nail & d Oak N 35	or m nd 26 . Oal k N s ron p lisc ii	ap profit for the N 30 55 W 2 56 pe n 28" (	' ne Sta '° W 3 23.16	te of I 4.3 1 21" (	Michig 8" Dak N	jan. T	he	9

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Set S&T SE side 36" Maple N 16° E 58.37 Set S&T W. side 14" Maple

2000 Michael Bartolo found 3/4" iron pipe

Nov. 11, 2000 I found 3/4" iron pipe with DEE cap. Dug to set Harrison monument but the 3/4" iron pipe must be wedged in the top of the 1 1/4" iron pipe as I couldn't get it out. I set a 5/8" X 3' re-rod inside of the 3/4" iron pipe and poured concrete around it. Placed a Lenawee County Re-mon cap stamped P.S. 13040 on the 5/8" re-rod.

1995 Dave Erickson found 3/4" iron pipe. Set DEE cap inside N 85° W 30.17 Set S&T N. side 29" Oak N 46° W 59.97

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

5/8" X 3' re-rod inside of 3/4" iron pipe over a 1 1/4" iron pipe in concrete with Lenawee County Re-mon cap stamped P.S. 13040 and is accepted as the best available evidence of the position of the original corner.

Fd dbl hd nail (added re-mon tag) in 30" Oak West 30.12 Fd nail & DEE tag in SW root of 36" Oak N 60° W 59.97 Fd. nail & DEE tag in W. face 16" Maple N 10° E 58.37 Set dbl hd nail & re-mon tag in E. face 13" Maple N 10° W 16.70 Carsonite witness post East 0.85 GLENN E.
RICHARD
No. 13040

GLENN E.
RICHARD
No. 13040

PAGE 25

LIBER 2

Ratified by Peer Group in accordance with P.A. 345 Co. Replemental Date November 28, 2000

igned by Menne. Richard Date Nov. 30, 2000

Glenn E. Richard

Surveyor's Michigan License No. 13040

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1971