

JAN 22 2001

Filed under Remonumentation Act 345 of 1990

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

SECTION

For corners in

Lenawee

(County)

Located In:

Corner Code #



LIBER 2

PAGE 29

1. Public Land Survey

T-6-S R-3-E

L-10

T R

T R

T R

T R

2. Property Controlling

S T R

in Section


S T R

3. Miscellaneous

S T R

Property in Sec

S T R



Register of Deeds Stamp & File Number

4. Lot No.

Recorded Plat

5. Private Claims

A B C D E F G H I J K L M

1														
2	6	5	4	3	2	1								
3														
4	7	8	9	10	11	12								
5														
6	18	17	16	15	14	13								
7														
8	19	20	21	22	23	24								
9														
10	30	29	28	27	26	25								
11														
12	31	32	33	34	35	36								
13														

I, Glenn E. Richard

in a field survey on November 22, 2000

do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

This position not established by original government surveyors.

Could not find any information on this corner prior to 1927

1927 Fred Soli P.S. 1090 surveyed the Girls Training School in Sections 25 and 26 for the State of Michigan and

"Set Monument" 14" Red Oak S 57° 30' E 36.0 12" Red Oak S 36° E 39.7 10" Red Oak S 46° 30' W 64.9

1957 MSHD found State of Michigan standard brass disc in iron pipe MSHD tag in 4" Oak N 12° E 10.53

1974 I found concrete monument with brass plate & recorded it in Liber 3, Page 77 MSHD tag in 10" Hackberry N 5° E

10.48. Nail & disc in following 30" Oak S 55° E 35.77. 24" Oak S 35° E 39.48. 22" Oak S 45° W 64.47.

1976 Werner Sommer found brass monument

2000 Michael Bartolo found brass disc in concrete N 5° E 10.47 fd. nail/brass washer E. face 12" Hickory.

S 60° E 35.68 Set nail/shiner N. root 40" Oak. S 15° W 19.18 Set nail/shiner E. face 12" Cherry

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

November 22, 2000 Found "State of Michigan" monument which checked witnesses. Set carsonite post 0.3 North

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

4" iron pipe with brass cap stamped "State of Michigan". This position not established by original government surveyors. This monument is accepted as the best available evidence of the position of the corner.


Found dbl hd nail & disc in 10" W. Cherry N 70° W 11.61

Found nail & brass disc in 12" Hackberry N 5° E 10.47

Found nail & brass disc in N root 40" Oak S 60° E 35.66

Found nail & disc in E. face 12" W. Cherry S 15° W 19.18

Carsonite witness post North 0.3



Ratified by Peer Group in accordance with P.A. 345

Co. Reg.

Glenn E. Richard

Date November 28, 2000

Signed by

Glenn E. Richard

Date Nov. 30, 2000

Glenn E. Richard

Surveyor's Michigan License No. 13040