

JAN 2 2 2001

Filed under Remonumentation Act 345 of 1990

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Lenawee

(County)


Located In:

Corner Code #



LIBER 2

PAGE 19



1. Public Land Survey

T-7-S R-2-E

A-6

T R

T R

T R

2. Property Controlling

S T R

in Section

S T R

3. Miscellaneous

S T R

Property in Sec

S T R

Register of Deeds Stamp & File Number

4. Lot No.

Recorded Plat

5. Private Claims

I, Glenn E. Richard

in a field survey on October 3, 2000

do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

This position not established by original government surveyors.

1865 Burton Kent surveyed Graves & Reed Addition to Clayton. Type of monumentation not given. The map shows "East & West middle Sec. 18, T7S R2E"

1870 Burton Kent surveyed the Northwest 1/4 of Section 18. Type of monumentation not given

Early 1900's J.L. Richard's red book record has witnesses but type of monumentation not given. Bolt in E. walk S 88° 45' E 32.6 NW corner Jurden's store S 71° 15' E 39.3 NE corner Judson & Hawkins Store N 78° 30' W 39.6

1927 John L. Richard surveyed Morey Hwy. and calls out West 1/4 post Section 18. Type of monument not given

1933 Walter E. Frazier surveyed Assessor's Plat No. 2 of Clayton Village with the West 1/4 corner Sec. 18 T7S, R2E, for the point of beginning. "Used point located from wit"

1975 I found P.K. nail in pavement. Bolt in walk East 32.64 NW corner of brick store S 71° E 39.25 NW corner of brick store N 78° W 39.65 nail and disc in EP N 35° E 44.95 and I recorded it in Liber 3, Page 288

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

October 3, 2000 Kevin Pickford P.S. 46682 found P.K. nail 3" deep in asphalt pavement. Found 1" iron pipe 14" deep 0.23 north and 0.03 east of the fd. P.K.. Set 5/8" X 3' re-rod 0.12 west of the found P.K. to be on line between M-6 and M-7 T7S R1E. Capped with Lenawee County Re-mon cap stamped P.S. 13040 and set monument box.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

5/8" X 3' re-rod with Lenawee County Remon cap stamped P.S. 13040 in monument box. This position not established by original government surveyors. This monument is accepted as the best available evidence of the position of the corner.

NW corner of conc. blk. garage N 69° E 66.23


SW corner of conc. blk. garage East 61.51

SE corner of brick store bldg S 34° W 68.09

NW corner of brick store bldg N 78° W 39.46

"X" cut on face of 4" steel post N 30° W 65.34

M-6 T7S R1E North 24.10



Ratified by Peer Group in accordance with P.A. 345

Co. Reg.

Glenn E. Richard

Date November 28, 2000

Signed by

Glenn E. Richard

Date

Nov. 30, 2000

Glenn E. Richard

Surveyor's Michigan License No. 13040