

SURVEY &  
REMONUMENTATION

SEP 03 1996

COMMISSION

Filed under Remonumentation Act 345 of 1990

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

LIBER 001 PAGE 111

For corners in

Lenawee  
(County)

Located In:

Corner Code #

1. Public Land Survey T 8 - S R 5 - E G-9  
T \_\_\_\_\_ R \_\_\_\_\_  
T \_\_\_\_\_ R \_\_\_\_\_  
T \_\_\_\_\_ R \_\_\_\_\_  
2. Property Controlling S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_  
in Section S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_  
3. Miscellaneous S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_  
Property in Sec S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_

4. Lot No. \_\_\_\_\_ Recorded Plat \_\_\_\_\_  
5. Private Claims \_\_\_\_\_

I, Glenn E. Richard, in a field survey on June 5 19 96, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

**NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.**

A. Description of original monument and accessories and/or subsequent restoration:

1820 Joseph Wampler set post corner Sections 21, 22, 27 & 28 Beech 14 N 86 W 13 Sycamore 12 N 11 E 19  
1881 James Blair found stake  
1882 James Blair found stake and stones  
1890 James Blair found stake and bricks  
1907 J.L. Richard survey record call for stake, bricks Maple 12" S 64 1/2 W 1.11 1/2 (73.59')  
1929 Walter Frazier set iron pin 2' east (for centerline of road) of the iron pipe marking a Section corner  
March 1975 K.L. Suydam found iron pipe 20" below the pavement and raised with a hex iron and recorded it in Liber 4, Page 154.  
1976 & 1983 W.E. Sommer found the hex iron as recorded in Liber 4, Page 154

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

June 5, 1996 The road is under re-construction. Found hex iron 12" deep bent.  
Dug deeper and found 1 1/4" I.P. 2' deep with bricks deeper around the I.P.  
Drove 3/4" X 3" gas pipe capped G.E.R. 13040 inside of the found 1 1/4" I.P. and it went down with the 3/4" gas pipe.  
June 26, 1996 Set monument box in new pavement.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

3/4" X 3" gas pipe capped G.E.R. 13040 over 1 1/4" I.P. in monument box and is accepted as the best available evidence of the position of the original corner.  
Found "X" cut on N. end C.M.P. N 40 W 36.54  
Found "X" cut on S. end C.M.P. S 50 W 33.41  
dbl. hd. nail & Re-mon tag in 36" Maple S 65 W 73.12  
dbl. hd. nail & Re-mon tag in E.P. S 10 E 156.03

Ratified by Peer Group in accordance with P.A. 345 Co. Rep. Glenn E. Richard Date 7-16-96

Signed by Glenn E. Richard Date 7-29-96  
Glenn E. Richard

Surveyor's Michigan License No. 13040

**FILED**

AUG 08 1996

LENAWEE COUNTY  
JEANETTE D. KNOX  
REGISTER OF DEEDS

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

