

JAN 16 5 2000

Filed under Remonumentation Act 345 of 1990
LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

LIBER 1 PAGE 357
STATE OF MICHIGAN
LENAWEE COUNTY
FILED

SECTION

For corners in Lenawee (County) Located In: Corner Code #

1. Public Land Survey T-8-S R-5-E J-3
T R
T R
T R

2. Property Controlling in Section S T R
S T R
S T R

3. Miscellaneous Property in Sec S T R

4. Lot No. _____ Recorded Plat _____

5. Private Claims _____

15 NOV 1999 9:55:24 AM

VICTORIA J. DANIELS
REGISTER OF DEEDS

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6	5	4	3	2								
3													
4	7	8	9	10	11	12							
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

I, Glenn E. Richard, in a field survey on October 5, 1999, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

- GLO 1820 Joseph Wampler set 1/4 Sec. post Ironwood 5 N 34 W 9 Sugar 11 S 55 E 10
- 1879 G.E. Kedzie found 1/4 post standing
- 1886 James Blair surveyed Section 2 and his survey calls for stake and stone
- 1958 I found 1/2" iron bar
- 1968 Walter Frazier and Associates found iron and raised with spike
- 1974 Walter Frazier and Associates found iron
- 1976 I found a 60d spike over iron pipe and raised with iron pipe and recorded it in Liber 3, Page 412

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Oct. 5, 1999 Found 1" X 22" iron pipe in monument box over 3/4" X 34" iron bar between stones on the east and west sides. Probed and hit bricks. Replaced the found irons with 5/8" X 3' re-rod with Lenawee County Re-mon cap stamped P.S. 13040

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

5/8" X 3' re-rod with Lenawee County Re-mon cap stamped P.S. 13040 in a monument box and is accepted as a careful and faithful perpetuation of the position of the original corner.

- Fd. dbl. hd. nail and added Lenawee County Re-mon tag in E.P. N 75° W 150.34
- Fd. dbl. hd. nail and added Lenawee County Re-mon tag in E.P. N 80° E 145.92
- Fd. "X" cut on W. end CMP N 55° W 28.23
- N.W. corner of brick hse. S 80° E 314.04

The corner is 1.5 North of pavement centerline



Ratified by Peer Group in accordance with P.A. 345 Co. Rep. Glenn E. Richard Date October 26, 1999

Signed by Glenn E. Richard Date Oct. 29, 1999
Glenn E. Richard

Surveyor's Michigan License No. 13040