

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

<u>Luce</u> (County)	Located In:	Corner Code #
1. Public Land Survey	T _____ R _____ T _____ R _____ T _____ R _____	_____ _____ _____
2. Property Controlling in Section	S 9 T 45N R 10W S 9 T 45N R 10W S _____ T _____ R _____	1 4 _____
3. Miscellaneous Property in Sec.	S _____ T _____ R _____ S _____ T _____ R _____	_____ _____
4. Lot No. _____, Recorded Plat		
5. Private Claims		

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

I, Stephan J. Szyszkoski, in a field survey on 4 11/29/2010 do hereby state  
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2  
above were in conformance with regulations and rules therefore as required in the current manual of survey  
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of  
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with  
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,  
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded  
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(1-Sec. 9) West 1/16 corner between Sections 4 and 9. Not established in the original survey.

(4-Sec. 9) Northwest 1/16 corner, Section 9. Not established in the original survey.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(1-Sec. 9) Established the corner midway and on the Section line between Section corner 1326.30' west  
and Quarter corner 1326.30' east.

(4-Sec. 9) Established the corner at the intersection of straight lines connecting opposite 1/16  
corners. From the position for the corner, a N-S mesh wire fence is 16' east.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(1) Set 1"IDx36" I.pipe with 4" alum. MDNR cap.  
Set measuring nail with MDNR tag in the side of:  
12" Cedar S89W 32.8' mrkd "W1/16 BT"  
5" Balsam S58W 3.15' do  
10" Cedar N15W 16.5' do  
6" B.Spruce N52E 23.45' do  
Bearings are magnetic.

(4) Set 1"IDx36" I.pipe with 4" alum. MDNR cap.  
Set measuring nail with MDNR tag in the side of:  
12" Y.Birch N70E 38.7' mrkd "NW1/16 BT"  
10" twin Maple S87E 32.4' do  
10" Basswood S58E 23.85' do  
3" R.Pine West 18.55' (no marks)  
Bearings are magnetic.

Signed by Stephan J. Szyszkoski  
Surveyor's Michigan License No. 33986

Date 03/10/2011

For the Michigan Department of Natural Resources, Office of Land and Facilities

