

FEB 23 2001

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970  
Luce County Remonumentation Corner

SECTION

For corners in

Luce County Located in: Corner Code #

1. Public Land Survey T45N R10W F/G-5 (East)  
T R  
T R #005  
T R  
2. Property Controlling S T R  
in Section S T R  
3. Miscellaneous S T R  
Property in Sec. S T R

4. Lot No. , Recorded Plat  
5. Private Claims

LUCE COUNTY

REGISTER OF DEEDS

Recorded

Lib 3 Page 958

02-12-2001 09:46:58

Kathy S. Mahar, Registrar

REGISTER OF DEEDS

Register of Deeds Stamp & File Number

I, Keith R. Waters, in a field survey on October 30, 2000, do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

F/G-5 (East) Meander Corner Common to Sections 9 & 16, T45N, R10W, on the East side of Mud Lake

1849 - Original corner established by William Ives, 10.80 chains (712.8 feet) west of the section corner G-5.

Witnesses: Tamarack 7, S40°E 13 links - Tamarack 12, N53°E 27 links.

Found no evidence of subsequent restoration of this corner.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

This corner is being reestablished as part of the Luce County Remonumentation Program.

Found no evidence of the original corner. Reestablished corner by single proportionate measurement on line between the Section corner at G-5 to the east and the meander corner on the west side of Mud Lake (also known as Tamarack Lake) to the west.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Placed a 1/2" x 48" rebar with a stamped aluminum Luce County Remonumentation cap at the corner location, which falls 32± from the water's edge of Mud (Tamarack) Lake.

Witnesses:

Nail and plastic witness tag #33142 in blazed 3" Cedar, S24°W 22.68'

Nail and plastic witness tag #33142 in blazed 4" Cedar, S19°E 12.22'

Nail and plastic witness tag #33142 in blazed 8" Tamarack, S63°E 28.29'

Nail and plastic witness tag #33142 in blazed 7" Tamarack, N43°E 57.16'

Signed by Keith R. Waters

Date 12-24-00

Surveyor's Michigan License No. 33142

