

FEB 23 2001

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

Luce County Remonumentation Corner

LUCE COUNTY

SECTION

For corners in

Luce County

Located in:

Corner Code #

- | | | | |
|------------------------------------|---|-----------|-----|
| 1. Public Land Survey | | T45N R10W | H-5 |
| | | T | R |
| | | T | R |
| | | T | R |
| 2. Property Controlling in Section | S | T | R |
| 3. Miscellaneous Property in Sec. | S | T | R |
| | S | T | R |

REGISTER OF DEEDS

Recorded

Liber 3 Page 960

02-12-2001 09:47:17

Keith R. Waters
REGISTER OF DEEDS

Register of Deeds Stamp & File Number

4. Lot No. , Recorded Plat
5. Private Claims

I, Keith R. Waters, in a field survey on September 12, 2000 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

- A. Description of original monument and accessories and/or subsequent restoration:

H-5 1/4 Corner Common to Sections 10 & 15, Town 45 North, Range 10 West

1849 – Original corner established by William Ives.

Witnesses: Spruce 6, N20°E 25 links – Cedar 11, S40°E 03 links.

1991 – Neil E. Hill, P.S. 27447, LCRC File No. 440, Luce County corner records. Found no evidence of corner or witnesses. Re-set corner midway and on line between section corners 1/2 mile east and 1/2 mile west. Found a small shallow creek meandering in many directions around trees. (GLO notes call for a stream, 3 links wide, 0.44 (29.04 feet) chains west of the corner). Set a 1/2" rod and cap #27447 in a 2" pipe. Witnesses:

7" Cedar, S50°E 8.78'

4" Cedar, N32°E 12.44'

5" Cedar, N75°W 11.99'

7" Cedar, N88°E 28.63'

- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

This corner is being perpetuated as part of the Luce County Remonumentation Program.

Found a 1/2" iron rod with cap #27447 in a 2" pipe and three of the record bearing trees as called for in the above mentioned 1991 LCRC, the fourth bearing tree has fallen down. Accepted corner as found and established an additional bearing tree.

- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Found a 1/2" iron rod with cap #27447 in a 2" iron pipe at the corner location.


Witnesses:

Nail and plastic witness tag #33142 in blazed 18" Cedar, S58°W 26.50'

Nail and brass M.D.O.T. witness tag in blazed 6" Cedar, N32°E 12.02'

Nail and brass M.D.O.T. witness tag in blazed 7" Cedar, N83°E 28.45'

Nail and brass M.D.O.T. witness tag in blazed 10" Cedar, N44°E 9.02'



Signed by Keith R. Waters

Date 12-29-00

Surveyor's Michigan License No. 33142