

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

<u>Luce</u> (County)	Located In:	Corner Code #
1. Public Land Survey	T _____ R _____	_____
	T _____ R _____	_____
	T _____ R _____	_____
2. Property Controlling in Section	S <u>27</u> T <u>45N</u> R <u>11W</u>	<u>8</u>
	S _____ T _____ R _____	(GCDB 420240)
	S <u>27</u> T <u>45N</u> R <u>11W</u>	<u>11</u>
	S _____ T _____ R _____	(GCDB 420220)
3. Miscellaneous Property in Sec.	S _____ T _____ R _____	_____
	S _____ T _____ R _____	_____
4. Lot No. _____, Recorded Plat	_____	_____
5. Private Claims	_____	_____

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

I, Stephan J. Szyszkoski, in a field survey on 06/04/14 do hereby state
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2
above were in conformance with regulations and rules therefore as required in the current manual of survey
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(8-Sec. 27) Center-West 1/16 corner, Section 27. Not previously monumented.

(11-Sec. 27) Southwest 1/16 corner, Section 27. Not previously monumented.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(8-Sec. 27) Established the position for the corner midway and on a straight line between Quarter
corner 1322.65' west and the intersection of 1/4 lines of Sec. 27 1322.65' east.

(11-Sec. 27) Established the position for the corner at the intersection of straight lines
connecting opposite 1/16 corners. From the position thus established, a N-S fenceline is 9 feet
west.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(8) Set 1"IDx30" I.pipe with 2" alum. MDNR cap.
Set measuring nail with MDNR tag in the side of:
8" Balsam N05°E 11.5' mrkd "W1/16 BT"
7" Balsam N76°E 21.0' do
14" W.Pine S28°E 42.3' do
12" Sugar S07°E 20.9' do
E= 8102417.175 N= 165741.443

(11) Set 1"IDx30" I.pipe with 2" alum. MDNR cap.
Set measuring nail with MDNR tag in the side of:
5" Sugar S50°E 14.45' mrkd "SW1/16 BT"
21" Sugar N50°E 15.85' do
6" Sugar N05°E 13.45' do
6" B.Ash S23°W 19.9' do
E= 8102426.866 N= 165340.569

Bearings are magnetic. Coordinates are MCS83 in meters (NAD83(2011) Datum)
Coord. Ref.=NGS PID D08495: N= 169938.252 m. E= 8114556.094 m.

Signed by Stephan J. Szyszkoski
Surveyor's Michigan License No. 33986

Date 06/16/2014

For the Michigan Department of Natural Resources, Forest Resources Division

