

LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A. 1970

Luce Co.

3 Corners.

FOR CORNERS OF --:	LOCATED IN --:	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY _____	T. <u>46</u> N. <u>9</u> R. <u>9</u> W.	<u>D-9</u>
2. PROPERTY CONTROLLING IN SECTION <u>19</u>	T. <u>46</u> N. <u>9</u> R. <u>9</u> W.	<u>9-Sec. 19</u> <u>6-Sec. 19</u>
3. MISCELLANEOUS PROPERTY IN SECTION _____	T. _____ N. _____ R. _____ E. _____	
4. LOT NO. _____, RECORDED PLAT _____		
5. PRIVATE CLAIMS _____		

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Billy D. Buckler, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on 2-10 & 1-30, 1975, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____, 19____, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

- D-9 Quarter Corner between Sec's. 20-29, set by Harvey Mallon, D.S. in 1850.
Bearings were: Maple 10, S74°E, 18 lks. and Hemlock 14, N69°W, 27 lks.
- 9-Sec.19 East 1/16 corner of section 19, T46N R9W.
- 6-Sec.19 Northeast 1/16 corner of section 19, T46N R9W.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

- D-9 Restored quarter corner between two section corners. Corner lies 6.15' West of a wood post.
- 9-Sec.19 Placed corner on line between $\frac{1}{4}$ corner to East and Center Corner to West.
- 6-Sec.19 Placed corner at center of the Northeast Quarter Section.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
Placed 1" pipe with 4" aluminium cap at all corners.

- D-9 New Bearings: 8" Spruce, S67°W, 12.0' & 8" R. Pine, S68°E, 16.0'.
Corner lies 6.15' West and 60.85' South of the wood post.
- 9-Sec.19 Bearings: 6" Cedar, S25°W, 28.0' and 8" Cedar, N79°E, 29.1'.
- 6-Sec.19 Bearings: 8" Cedar, South, 212 lks.

SIGNED BY

Billy D. Buckler
Billy D. Buckler

DATE 2-16-79

SURVEYOR'S MICHIGAN REGISTRATION NO. 8887

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY

CHIEF OF SURVEY PARTY

DATE

APPROVED AND SIGNED BY

MICHIGAN REGISTERED LAND SURVEYOR

DATE

(SEAL)

SURVEYOR'S MICHIGAN REGISTRATION NO. _____

