

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

	Luce	Located In:	Corner Code #
	(County)		
1. Public Land Survey		T R	
		T R	
		T R	
2. Property Controlling in Section	S 5	T 46N R 10W	15
	S 5	T 46N R 10W	11
		T R	
3. Miscellaneous Property in Sec.	S	T R	
	S	T R	

4. Lot No. , Recorded Plat
5. Private Claims

I, Stephan J. Szyszkoski, in a field survey on 15 07/01/2010 do hereby state
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2
above were in conformance with regulations and rules therefore as required in the current manual of survey
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(15-Sec. 5) West 1/16 corner between Sections 5 and 8. Not established in the original survey.

(11-Sec. 5) Southwest 1/16 corner, Section 5. Not established in the original survey.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(15-Sec. 5) Established the corner midway and on the Section line between Section corner 1317.77'
west and Quarter corner 1317.77' east.

(11-Sec. 5) Established the corner at the intersection of straight lines connecting opposite 1/16
corners. The position for the corner falls about 10' south of the corner of a plantation (Pine to NW
and Spruce to NE).

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(15) Set 1"IDx36" I.pipe with 4" alum. MDNR cap.
Set measuring nail with MDNR tag in the side of:
4" B.Spruce S82W 11.9' mrkd "W1/16 BT"
7" Cedar N61W 20.95' do
9" Maple N56E 22.25' do
26" W.Pine S66E 46.35' do
Bearings are magnetic.

(11) Set 1"IDx36" I.pipe with 4" alum. MDNR cap.
Set measuring nail with MDNR tag in the side of:
11" W.Spruce N43E 26.0' mrkd "SW1/16 BT"
15" R.Pine N30W 69.5' do
12" Cherry in clump N48W 65.25' do
7" W. Pine N88W 32.35' do
Bearings are magnetic.

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	10		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

Signed by Stephan J. Szyszkoski
Surveyor's Michigan License No. 33986

Date 10/26/2010

For the Michigan Department of Natural Resources and Environment, Forest Management Division

