

# LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A. 1970  
Luce Co. Four Corners.

FOR CORNERS OF:-	LOCATED IN:-	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY	T. 47 N. R. 10 W.	D-6
2. PROPERTY CONTROLLING IN SECTION 17	T. 47 N. R. 10 W.	12, Sec. 17 11, Sec. 17 13, Sec. 17
3. MISCELLANEOUS PROPERTY IN SECTION	T. N. R. W.	
4. LOT NO.	RECORDED PLAT	
5. PRIVATE CLAIMS		

REGISTER OF DEEDS STAMP AND  
FILING NUMBER

I, Billy D. Buckler do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above (identified with circles on index code diagram - over) were, in a field survey on 8-7 1973, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on 19, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

D-3 Center Corner, Section 17.  
12, Sec. 17 South 1/16 Corner, Section 17.  
11, Sec. 17 S.W. 1/16 Corner, Section 17.  
13, Sec. 17 S.E. 1/16 Corner, Section 17.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

D-3 Corner placed at intersection of lines, connecting opposite quarter cors.  
12, Sec. 17 Corner placed midway bet. Center corner, to North and quarter Cor. to South.  
11, Sec. 17 Corner placed at intersection of lines, quartering the South-West, quarter section.  
13, Sec. 17 Corner placed at intersection of lines, quartering the South-East, quarter section.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:  
Placed 1" pipe with 4" aluminium caps at all four corners.

New Witnesses:

D-3 8" Y. Birch, S66°W, 5.1' and 8" Maple, N79°E, 12.3'  
12, Sec. 17 10" S. Maple, S32°W, 27.4' and 8" S. Maple, N53°W, 26.6'  
11, Sec. 17 10" H. Maple, S39°W, 13.9' and 6" H. Maple, N70°W, 33.1'  
13, Sec. 17 10" W. Birch, N47°W, 34.7' and 10" Beech, S63°W, 11.6'

SIGNED BY Billy D. Buckler

DATE 2-22-74

SURVEYOR'S MICHIGAN REGISTRATION NO. 8887

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY \_\_\_\_\_ CHIEF OF SURVEY PARTY

DATE \_\_\_\_\_

APPROVED AND SIGNED BY \_\_\_\_\_ MICHIGAN REGISTERED LAND SURVEYOR

DATE \_\_\_\_\_

SURVEYOR'S MICHIGAN REGISTRATION NO. \_\_\_\_\_

