

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 47 N. R. 9-10W


Leice COUNTY

DESCRIPTION OF CORNER Section Corner common to Secs. 30-31-25-36

CORNER MONUMENT 1" Pine with 4" Brass Cap

DATE MONUMENT PLACED AND WITNESSED 7/2/63

WITNESSES TO CORNER..... 8" Jackpine (S31 NBT) S23°E 15 lks.



7" Jackpine (S25 NBT) W46°W 13 lks.

8" Jackpine (S30 NBT) N56°E 43 lks.

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This Corner was replaced at an old Scribed Wood Post probably set by H. Lawrence, Registered Land Surveyor. Found Tamarack B.T. (down) bearing N63°E 14 Links. Placed Location Poster 11½ Chains South of Corner on Road.

SURVEYOR'S SEAL

SIGNED Billy D. Buckler DATE 7/31/1964
REGISTERED LAND SURVEYOR