## MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

## LAND CORNER RECORD

DESCRIPTION OF CORNER 1/4 corner between Sections 30 and 31

CORNER HONUMENT 1" Pipe with 4" Brass Cap

DATE MONUMENT PLACED AND WITHESSED 10/26/60 with George Hamilton, Assit.

WITHESSES TO CORNER....16" W. Spruce (1/4s NBT) S 66° E 101 Links

15" W. Pine (1/4s NBT) N 62° W 182 Links

DESCRIPTION IN DETAIL AS TO NOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was re-established by single proportionate measure between Two Section Corners. No evidence of original corners.

SURVEYOR'S SEAL

CIRCLE CORNER REGISTERED

SIGNED Silly D. Suckles DATE 5/31/61

REGISTERED LAND SURVEYOR

Billy D. Buckler