

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

| <u>Luce</u><br>(County)               | Located In:                                                                                               | Corner Code #                   |
|---------------------------------------|-----------------------------------------------------------------------------------------------------------|---------------------------------|
| 1. Public Land Survey                 | T _____ R _____<br>T _____ R _____<br>T _____ R _____                                                     | _____<br>_____<br>_____         |
| 2. Property Controlling<br>in Section | S <u>32</u> T <u>47N</u> R <u>10W</u><br>S <u>32</u> T <u>47N</u> R <u>10W</u><br>S _____ T _____ R _____ | <u>10</u><br><u>11</u><br>_____ |
| 3. Miscellaneous<br>Property in Sec.  | S _____ T _____ R _____<br>S _____ T _____ R _____                                                        | _____<br>_____                  |
| 4. Lot No. _____, Recorded Plat _____ |                                                                                                           |                                 |
| 5. Private Claims                     |                                                                                                           |                                 |

Register of Deeds Stamp & File Number

|    | A  | B | C  | D | E  | F | G  | H | I  | J | K  | L | M |
|----|----|---|----|---|----|---|----|---|----|---|----|---|---|
| 1  |    |   |    |   |    |   |    |   |    |   |    |   |   |
| 2  | 6  |   | 5  |   | 4  |   | 3  |   | 2  |   | 1  |   |   |
| 3  |    |   |    |   |    |   |    |   |    |   |    |   |   |
| 4  | 7  |   | 8  |   | 9  |   | 10 |   | 11 |   | 12 |   |   |
| 5  |    |   |    |   |    |   |    |   |    |   |    |   |   |
| 6  | 18 |   | 17 |   | 16 |   | 15 |   | 14 |   | 13 |   |   |
| 7  |    |   |    |   |    |   |    |   |    |   |    |   |   |
| 8  | 19 |   | 20 |   | 21 |   | 22 |   | 23 |   | 24 |   |   |
| 9  |    |   |    |   |    |   |    |   |    |   |    |   |   |
| 10 | 30 |   | 29 |   | 28 |   | 27 |   | 26 |   | 25 |   |   |
| 11 |    |   |    |   |    |   |    |   |    |   |    |   |   |
| 12 | 31 |   | 32 |   | 33 |   | 34 |   | 35 |   | 36 |   |   |
| 13 |    |   |    |   |    |   |    |   |    |   |    |   |   |

I, Stephan J. Szyszkoski, in a field survey on 11/02/2011 do hereby state  
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2  
above were in conformance with regulations and rules therefore as required in the current manual of survey  
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of  
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with  
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,  
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded  
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(10-Sec. 32) South 1/16 corner between Sections 31 and 32. Not previously monumented.

(11-Sec. 32) Southwest 1/16 corner, Section 32. Not previously monumented.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(10-Sec. 32) Established the position for the corner midway and on the Section line between Section  
corner 1313.11' south and Quarter corner 1313.11' north.

(11-Sec. 32) Established the position for the corner at the intersection of straight lines connecting  
opposite 1/16 corners.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(10) Set 1"IDx36" I.pipe with 4" alum. MDNR cap.  
Set measuring nail with MDNR tag in the side of:  
8" W.Spruce S79E 72.15' mrkd "S1/16 BT"  
12" W.Pine S06W 35.8' do  
16" R.Pine S33W 67.2' do  
8" W.Birch S80W 55.55' do  
2-track road 10' east  
Sq'd pine post adjacent.  
Bearings are magnetic.

(11) Set 1"IDx36" I.pipe with 4" alum. MDNR cap.  
Set measuring nail with MDNR tag in the side of:  
12" Maple S43W 8.2' mrkd "SW1/16 BT"  
17" W.Birch S30E 19.95' do  
7" Balsam N39E 6.1' do  
21" twin Sugar N72W 22.8' do  
Bearings are magnetic.

Signed by Stephan J. Szyszkoski  
Surveyor's Michigan License No. 33986

Date 02/14/2012

For the Michigan Department of Natural Resources, Forest Resources Division

