

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

<u>Luce</u> (County)	Located In:	Corner Code #
1. Public Land Survey	T _____ R _____ T _____ R _____ T _____ R _____	_____
2. Property Controlling in Section	S <u>32</u> T <u>47N</u> R <u>10W</u> S _____ T _____ R _____ S _____ T _____ R _____	<u>15</u>
3. Miscellaneous Property in Sec.	S _____ T _____ R _____ S _____ T _____ R _____	_____
4. Lot No. _____, Recorded Plat _____		
5. Private Claims		

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

I, Stephan J. Szyszkoski, in a field survey on 11/08/2011 do hereby state
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2
above were in conformance with regulations and rules therefore as required in the current manual of survey
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(15-Sec. 32) West 1/16 corner between Section 32 T47N-R10W and Section 5 T46N-R10W. Not previously
monumented.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(15-Sec. 32) Established the position for the corner midway and on the township line between Section
corner 1323.35' west and Quarter corner 1323.35' east. The corner position falls approx. 23' south
of the centerline of an E-W gravel road.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(15) Set 1"IDx36" I.pipe with 4" alum. MDNR cap.
Set measuring nail with MDNR tag in the side of:
11" Cherry S65E 20.0' mrkd "W1/16 BT"
15" Maple N39E 92.17' do
Power pole N64W 168.09'
Power pole N81E 234.07'
Bearings are magnetic.
Squared pine post adjacent.



Signed by Stephan J. Szyszkoski
Surveyor's Michigan License No. 33986

Date 02/14/2012

For the Michigan Department of Natural Resources, Forest Resources Division