

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Luce

(County)

Located In:

Corner Code #

1. Public Land Survey

T R

T R

T R

S.30 T.47N R.10W

7

2. Property Controlling in Section

S T R

S T R

3. Miscellaneous Property in Sec.

S T R

S T R

4. Lot No. , Recorded Plat

5. Private Claims

Register of Deeds Stamp & File Number

I, Stephan J. Szyszkoski, in a field survey on June 20, 2007 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(7-Sec. 30) North 1/16 between Sections 29 and 30. Not established in the original survey.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(7-Sec. 30) Established the corner midway and on the Section line between Section corner 1320.75' north and Quarter corner 1320.75' south. The position for the corner falls in the ditch line on the west side of County Road 407.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(7-Sec. 30) Set 1"IDx36" I.pipe with plastic cap stamped MICH DNR LS33986", flush with surface of the ground. Set measuring nails in:  
5" W.Birch S17W 19.4' mrkd "N1/16 BT"  
6" W.Birch N14W 35.4' do  
18" R.Pine N72W 78.4' do  
8" W.Birch N79E 68.57' do  
Bearings are magnetic. Distances are to nail with MDNR tag in side of tree.



Signed by

Stephan J. Szyszkoski

Date

12/20/07

Surveyor's Michigan License No. 33986