

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

<u>Luce</u> (County)	Located In:	Corner Code #
1. Public Land Survey	T R	
	T R	
	T R	
2. Property Controlling in Section	S 7 T 49N R 10W	8
	S 7 T 49N R 10W	11
	S T R	
3. Miscellaneous Property in Sec.	S T R	
	S T R	
4. Lot No. _____, Recorded Plat		
5. Private Claims		

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

I, Stephan J. Szyszkoski, in a field survey on 8 04/07/2011 do hereby state
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2
above were in conformance with regulations and rules therefore as required in the current manual of survey
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(8-Sec. 7) West 1/16 corner, Section 7. Not established in the original survey.

(11-Sec. 7) Southwest 1/16 corner, Section 7. Not established in the original survey.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(8-Sec. 7) Established the corner on the E-W 1/4 line of Section 7 1171.00' east of 1/4 corner A4 and
1322.33' west of Center of Section B4, proportionate to the protraction derived from the dimensions
given on the face of the original plat: 17.680 chains east of A4 and 19.965 chains west of B4.

(11-Sec. 7) Established the corner at the intersection of straight lines connecting opposite 1/16
corners.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(8) Set 1"IDx36" I.pipe with 4" alum. MDNR cap.
Set measuring nail with MDNR tag in the side of:
13" R.Pine S61E 7.25' mrkd "W1/16 BT"
4" W.Pine N05W 8.1' do
9" R.Pine N78W 33.0' do
11" R.Pine S34W 13.75' do
Bearings are magnetic.

(11) Set 1"IDx36" I.pipe with 4" alum. MDNR cap.
Set measuring nail with MDNR tag in the side of:
11" W.Pine N85E 21.8' mrkd "SW1/16 BT"
10" W.Pine N06E 10.1' do
8" W.Birch N40W 10.0' do
13" W.Pine S21W 19.25' do
Bearings are magnetic.

Signed by

Stephan J. Szyszkoski
Surveyor's Michigan License No. 33986

Date

05/04/2011

For the Michigan Department of Natural Resources, Office of Land and Facilities



47470

47471

FORM APPROVED BY MICHIGAN STATE BOARD

1971
14, 1975
Jan., 1983
Revised Oct., 1995