

LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A. 1970
Luce Co. Three Corners.

| FOR CORNERS OF-- | LOCATED IN-- | CORNER CODE NUMBER |
|--------------------------------------|---------------------|---------------------------------|
| 1. PUBLIC LAND SURVEY | T. 50 N. R. 9 E. | G-12 7-Sec. 33 14-Sec. 33 |
| 2. PROPERTY CONTROLLING IN SECTION | 33 T. 50 N. R. 9 E. | |
| 3. MISCELLANEOUS PROPERTY IN SECTION | T. N. R. E. | |
| 4. LOT NO. | RECORDED PLAT | |
| 5. PRIVATE CLAIMS | | |

REGISTER OF DEEDS STAMP AND
FILING NUMBER

I, Billy D. Buckler do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above (identified with circles on index code diagram - over) were, in a field survey on 1/17 1972, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on 19, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

G-12 Corner bet. Secs: 33-34, set by Harvey Mellen, D.S. 1850.
Bearings were: Maple 10" S62°E 40 lks and Y. Pine 14" N23°W 1.27 cns.

7-Sec. 33 North 1/16 Corner, on East side, Sec. 33.

14-Sec. 33 South 1/16 Corner, on East side, Sec. 33.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

G-12 Cor. re-established midway and on line bet. two Sec. Cors.
Corner lies in center of N-S firelane.

7-Sec. 33 Corner established midway and on line, bet. Sec. Cor. to North and 1/4 Cor. to South and in center of N-S firelane.

14-Sec. 33 Cor. established midway and on line bet. 1/4 Cor. to North and Sec. Cor. to South. Corner lies on West edge of N-S firelane.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

1" pipe with 4" aluminium cap set at all three corners.

G-12 New bearings: 8" Jack Pine S28°W 44.2' and 10" Jack Pine S66°E 32.7'

7-Sec. 33 Bearings: 12" Jack Pine N37°E 48.2' and 10" Jack Pine S77°E 24.0'

14-Sec. 33 Bearings: 9" Jack Pine S85°E 13.1' and 7" Jack Pine S39°E 27.3'

SIGNED BY

Billy D. Buckler
Billy D. Buckler

DATE 1/4/73

SURVEYOR'S MICHIGAN REGISTRATION NO.

8887

(SEAL)

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY

CHIEF OF SURVEY PARTY

DATE

APPROVED AND SIGNED BY

MICHIGAN REGISTERED LAND SURVEYOR

DATE

(SEAL)

SURVEYOR'S MICHIGAN REGISTRATION NO.

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 28, 1971
DISTRIBUTED BY MICHIGAN SOCIETY OF REGISTERED LAND SURVEYORS