

LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

Luce Co.

2 Corners.

FOR CORNERS OF--	LOCATED IN--	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY_____	T. 50 ^{N.} X. , R. 12 ^{X.} W.	A-12, A-12A
2. PROPERTY CONTROLL- ING IN SECTION_____	, T. _____ ^{N.} S. , R. _____ ^{E.} W.	
3. MISCELLANEOUS PROPERTY IN SECTION_____	, T. _____ ^{N.} S. , R. _____ ^{E.} W.	
4. LOT NO. _____, RECORDED PLAT _____		
5. PRIVATE CLAIMS _____		

REGISTER OF DEEDS STAMP AND
FILING NUMBER

I, Billy D. Buckler, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on 6/26, 1975, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____, 19____, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

Corners set by Francis Colman, D.S. in 1851.

A-12 Quarter Corner on Westside of Section 31. Bearings were: N.Pine 6", S21°W, 22 lks & N.Pine 6", N12°W, 25 lks.

A-12A Witness Corner to Meander Corner on Westside of Section 31. Bearings to Meander Corner were: N.Pine 9", S18°E, 47 lks. and N.Pine 6", S48°W, 43 lks.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

A-12 Corner re-established at record distance North of twp. corner and on same bearing as the mile South. No evidence of original corner. Found a wood post 11.3' West and 2.0' North.

A-12A Witness to Meander set on the Twp. line, extended from the South at 1,364.0' North of the quarter corner. Record = 1,568.8'. Erosion has moved bluff in land 200'.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Placed 1" pipe with 4" aluminium cap at both corners.

A-12 New Bearings: 6" J. Pine, N75°E, 11.4' and 6" J. Pine, S78°W, 15.3'.

A-12A New Bearings: 8" J. Pine, S41°W, 44.7' and 8" J. Pine, S23°E, 33.9'.
Corner is 20' South of top of bluff.

SIGNED BY Billy D. Buckler

Billy D. Buckler

SURVEYOR'S MICHIGAN REGISTRATION NO. 8887

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ DATE _____

CHIEF OF SURVEY PARTY

APPROVED AND SIGNED BY _____ DATE _____

MICHIGAN REGISTERED LAND SURVEYOR

(SEAL)

SURVEYOR'S MICHIGAN REGISTRATION NO. _____

