

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

9-
FILED

For corners in

LIVINGSTON
(County)

Located In:

Corner Code #

1996 NOV 14 P 1:20

NANCY HAVILAND
REGISTER OF DEEDS
LIVINGSTON COUNTY, MI.
40643

L.S.C. #585m
Register of Deeds Stamp & File Number

1. Public Land Survey T 1N R 3E C-10
T R
T R
T R
2. Property Controlling S T R
in Section S T R
3. Miscellaneous S T R
Property in Sec. S T R

4. Lot No. , Recorded Plat
5. Private Claims

I, DARRELL HUGHES, in a field survey on 11-11, 19 96 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

| | A | B | C | D | E | F | G | H | I | J | K | L | M |
|----|---|----|---|----|---|----|---|----|---|----|---|----|---|
| 1 | | | | | | | | | | | | | |
| 2 | | 6 | | 5 | | 4 | | 3 | | 2 | | 1 | |
| 3 | | | | | | | | | | | | | |
| 4 | | 7 | | 8 | | 9 | | 10 | | 11 | | 12 | |
| 5 | | | | | | | | | | | | | |
| 6 | | 18 | | 17 | | 16 | | 15 | | 14 | | 13 | |
| 7 | | | | | | | | | | | | | |
| 8 | | 19 | | 20 | | 21 | | 22 | | 23 | | 24 | |
| 9 | | | | | | | | | | | | | |
| 10 | | 30 | | 29 | | 28 | | 27 | | 26 | | 25 | |
| 11 | | | | | | | | | | | | | |
| 12 | | 31 | | 32 | | 33 | | 34 | | 35 | | 36 | |
| 13 | | | | | | | | | | | | | |

UNADILLA

A. Description of original monument and accessories and/or subsequent restoration:

GLO: 1825
Black Oak 8", Due East, 28 links
Black Oak 10", South 10 degrees West, 15 links

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found 1/2" iron rod in centerline of Doyle Road

*Additional descriptions and historical information on back of this sheet.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

C-10, T1N, R3E, UNADILLA, replaced existing corner with 1-1/4" X 36" iron pipe, affixed with 2" dia. brass cap, stamped "Livingston Co. Monumentation Corner, P.S. 19834, and is accepted as a careful and faithful perpetuation of the position of the original corner.
262 DEG. 114.53' SET NAIL/TAG N/S 16" ELM.
069 DEG. 54.15' SET NAIL/TAG SE/S 42" OAK.
325 DEG. 33.01' SET NAIL/TAG E/S 48" SYCAMORE.
178 DEG. 21.59' SET NAIL/TAG W/S 10" HICKORY.
002 DEG. 27.49' FACE OF IRON FENCE END POST.

Signed by [Signature]
Surveyor's Michigan License No. 19834

Date November 11, 1996

P.A. 345 1990, APPROVED BY LIVINGSTON COUNTY
PEER GROUP ON 10-7-96 CO. REP SED

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971
REVISED MAY 14, 1975
REVISED JAN., 1983
REVISED OCT., 1995

UNADILLA TOWNSHIP, T1N, R3E

C-10, WEST 1/4 COR. SEC. 29 AND EAST 1/4 COR. SEC. 30.

FIELD: 7-9-1996 DARRELL D. HUGHES AND ASSOCIATES.

Found 1/2" iron rod, 0.3' below gravel road grade, centerline Doyle Road. Fence and tree row to North. Three older witness distances check. Good for GPS. I recommend, to the peer group, the acceptance of this iron rod for the location of C-10.

1825 Sylvester Sibley, U.S. Deputy Surveyor, "North between 29 and 39, 40.00 chains, set 1/4 sec. post". P.7

1972 Clifford Smith files Act 74 for MDOT. P.8

1972? Oscar Boss shows corner in survey. P.9

1972 Oscar Boss uses corner in survey. P.10

1996 Witness list. P.11