

FILED

OCT 16 11 44 AM '95

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

NANCY HAVILAND  
REGISTER OF DEEDS  
LIVINGSTON COUNTY, MI  
48843

or corners in

LIVINGSTON

(County)

Located In:

Corner Code ##

Public Land Survey

T 1N R 4E

L-9

T R

T R

T R

T R

Property Controlling  
in Section

S T R

S T R

Miscellaneous

S T R

Property in Sec.

S T R

L.S.C. # 501m

Register of Deeds Stamp & File Number

Lot No. , Recorded Plat

Private Claims

DARRELL HUGHES, in a field survey on OCT 4 JANUARY 24, 19 95

hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

Description of original monument and accessories and/or subsequent restoration:

GLO: 1823, Joseph Wampler, Deputy Surveyor  
White Oak 11", South 42 degrees East, 46 links  
White Oak 20", North 48 degrees West, 119 links

SURVEY &  
REMONUMENTATION

NOV 27 1995

COMMISSION

Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found 1/2 inch iron pipe at fence intersection

\*Additional descriptions and historical information on back of this sheet.

Description of monument for corner and accessories established to perpetuate locating the position of the corner:

L-9, T1N, R4E, PUTNAM, replaced existing corner with 1-1/4" X 36" iron pipe, affixed with 2" dia. brass cap, stamped "Livingston Co. Monumentation Corner, P.S. 19834, and is accepted as a careful and faithful reestablishment of the position of the original corner.  
005 DEG. 20.78' SET NAIL/TAG E/S 27" OAK.  
049 DEG. 22.80' SET NAIL/TAG NW/S 6" OAK.  
126 DEG. 18.18' SET NAIL/TAG N/S 24" TWIN OAK.  
264 DEG. 24.23' SET NAIL/TAG S/S 6" MAPLE.

igned by

Date October 5, 1995

Surveyor's Michigan License No. 19834

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971  
REVISED MAY 14, 1975  
REVISED JAN., 1983

P.A. 345 1980, APPROVED BY LIVINGSTON COUNTY

PUTNAM TOWNSHIP, T1N, R4E

L-9, NORTH 1/4 COR. SEC. 25, SOUTH 1/4 COR. SEC. 24

FIELD: FEBRUARY 1995

FOUND 1/2" IRON PIPE IN N-S-E FENCE LINE INTERSECTION. WITNESS' CHECK  
BOSS. (P.15) MEASURES WEST TO K-9 2598.90' BOSS 77-79, 2598.37' HUGHES  
95, 2600.4 BULLOCK 1874, 2582.58' GLO 1823. NOT GOOD FOR GPS.

1823 Corner first set by Joseph Wampler, U.S. Deputy Surveyor at 39.13  
chains (2582.58'). P.7

1837 Amos Adams, County Surveyor, surveys NW 1/4 of NE 1/4 Sec. 25. P.8

1873 Miles Bullock, County Surveyor, surveys N-S 1/4 line Sec.25. P.9

1874 Miles Bullock, County Surveyor, surveys and divides Sec. 25.  
P.10-11

1973 Oscar Boss finds 1/2" pipe. P.12 and files Act 74, P.13

1977-1979 Gary Boss surveys using same pipe. P.14-14G

1995 Hughes witness to corner. P.15