

**FEB 26 2001**

**SECTION**

**LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970**

**FILED**

For corners in

|                                       |                            |               |
|---------------------------------------|----------------------------|---------------|
| <u>LIVINGSTON</u><br>(County)         | Located In:                | Corner Code # |
| 1. Public Land Survey                 | <u>T1N R4E</u>             |               |
|                                       | <u>T</u> <u>R</u>          |               |
|                                       | <u>T</u> <u>R</u>          |               |
|                                       | <u>T</u> <u>R</u>          |               |
| 2. Property Controlling<br>in Section | <u>S</u> <u>T</u> <u>R</u> |               |
|                                       | <u>S</u> <u>T</u> <u>R</u> |               |
| 3. Miscellaneous<br>Property in Sec.  | <u>S16</u> <u>T1N R4E</u>  | <u>001</u>    |
|                                       | <u>S16</u> <u>T1N R4E</u>  | <u>002</u>    |
| 4. Lot No. _____, Recorded Plat _____ |                            |               |
| 5. Private Claims _____               |                            |               |

**2000 SEP 28 10 41 18**

**NANCY HAVILAND  
REGISTER OF DEEDS  
LIVINGSTON COUNTY, MI.  
48843**

**LSC #1276m  
Register of Deeds Stamp & File Number**

I, JACK K. SMITH, in a field survey on AUGUST 25, 2000 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

|    |   |    |   |    |   |    |   |    |   |    |   |    |   |
|----|---|----|---|----|---|----|---|----|---|----|---|----|---|
| 1  | A | B  | C | D  | E | F  | G | H  | I | J  | K | L  | M |
| 2  |   | 6  |   | 5  |   | 4  |   | 3  |   | 2  |   | 1  |   |
| 3  |   |    |   |    |   |    |   |    |   |    |   |    |   |
| 4  |   | 7  |   | 8  |   | 9  |   | 10 |   | 11 |   | 12 |   |
| 5  |   |    |   |    |   |    |   |    |   |    |   |    |   |
| 6  |   | 18 |   | 17 |   | 16 |   | 15 |   | 14 |   | 13 |   |
| 7  |   |    |   |    |   |    |   |    |   |    |   |    |   |
| 8  |   | 19 |   | 20 |   | 21 |   | 22 |   | 23 |   | 24 |   |
| 9  |   |    |   |    |   |    |   |    |   |    |   |    |   |
| 10 |   | 30 |   | 29 |   | 28 |   | 27 |   | 26 |   | 25 |   |
| 11 |   |    |   |    |   |    |   |    |   |    |   |    |   |
| 12 |   | 31 |   | 32 |   | 33 |   | 34 |   | 35 |   | 36 |   |
| 13 |   |    |   |    |   |    |   |    |   |    |   |    |   |

A. Description of original monument and accessories and/or subsequent restoration:

GLO 1825 JOSEPH WAMPLER SET POST  
POST IN POND

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

F-05 NO CORNER WAS PLACED DUE TO LAKE. THE ONLY POSITION USED PREVIOUSLY HAS BEEN AT 1/2 THE DISTANCE ON LINE BETWEEN E-05 AND G-05. SET 2 REFERENCE MONUMENTS PLACED EASTERLY AND SOUTHERLY OF COMPUTED POSITION OF F-05 ON LINE WITH E-05 AND G-05.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

-001  
EASTERLY REFERENCE MONUMENT W/ BRASS REMON WITNESS CAP 13' SOUTH OF CENTERLINE +/- OF DAM TRAIL (ON LINE BETWEEN F-05 AND G-05 AND DISTANT S86°57'31"E 240.00 FEET FROM THE COMPUTED POSITION OF F-05)  
S50°W SPIKE AND REMON TAG ON NORTH SIDE OF 8" TWIN OAKS 50.57'  
S70°W MAG NAIL IN TOP, CENTER OF FIRST STEEL POST SOUTH OF TRAIL 25.92'  
N80°W MAG NAIL IN TOP, CENTER OF FIRST STEEL POST NORTH OF TRAIL 32.20'

-002  
SOUTHERLY REFERENCE MONUMENT W/ BRASS REMON WITNESS CAP 9' SOUTH OF CENTERLINE +/- OF DAM TRAIL (ON LINE BETWEEN F-05 AND F-06 AND DISTANT S00°08'07"W 350.00 FEET FROM THE COMPUTED LOCATION OF F-05)  
S40°E CENTER LINE OF 5 FOOT HIGH 2" STEEL POST 21.77'  
S30°W SPIKE AND REMON TAG ON NORTH SIDE OF 14" POPLAR 66.95'  
S70°W SPIKE AND REMON TAG ON SOUTH SIDE OF 14" POPLAR 86.45'  
WEST SOUTHEAST CORNER OF CONCRETE DAM OUTLET STRUCTURE 86.15'

Signed by [Signature] Date 9-15-2000

Surveyor's Michigan License No. 35999

**P.A. 345 1980, APPROVED BY LIVINGSTON COUNTY**

**PROF GROUP ON 2-2-2000 CO REP JED**

