

SURVEY & REMONUMENTATION

FEB 26 2001

SECTION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

<u>LIVINGSTON</u>	Located In:	Corner Code #
(County)		
1. Public Land Survey	T <u>1</u> N R <u>4</u> E	<u>G-05</u>
	T <u> </u> R <u> </u>	<u> </u>
	T <u> </u> R <u> </u>	<u> </u>
	T <u> </u> R <u> </u>	<u> </u>
2. Property Controlling	S <u> </u> T <u> </u> R <u> </u>	<u> </u>
in Section	S <u> </u> T <u> </u> R <u> </u>	<u> </u>
3. Miscellaneous	S <u> </u> T <u> </u> R <u> </u>	<u> </u>
Property in Sec.	S <u> </u> T <u> </u> R <u> </u>	<u> </u>

2000 SEP 28 A 9:18

NANCY HAVILAND
REGISTER OF DEEDS
LIVINGSTON COUNTY, MI.
48843

LSC #1279m

Register of Deeds Stamp & File Number

4. Lot No. , Recorded Plat
5. Private Claims

I, JACK K. SMITH, in a field survey on AUGUST 25, 2000 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

1	A	B	C	D	E	F	G	H	I	J	K	L
2		6		5		4		3		2		1
3												
4		7		8		9		10		11		12
5												
6		18		17		16		15		14		13
7												
8		19		20		21		22		23		24
9												
10		30		29		28		27		26		25
11												
12		31		32		33		34		35		36
13												

A. Description of original monument and accessories and/or subsequent restoration:

GLO 1825 JOSEPH WAMPLER SET POST
WHITE OAK 13" S21°E 54.78'
WHITE OAK 10" N55°W 89.10'

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

THE EXISTING CORNER IS A 4" CONCRETE MONUMENT WITH AN ALUMINUM DNR CAP (DONALD BISSELL) 1/2 FOOT BELOW THE SURROUNDING GROUND 2 FEET WEST OF THE WEST EDGE OF A GRAVEL DRIVEWAY ON LINE WITH CEDAR LAKE ROAD (GRAVEL TO THE SOUTH). DISTANCES TO THE EAST, WEST AND SOUTH COMPARE WELL.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

G-05 NORTHEAST CORNER SECTION 16, T1N, R4E, PUTNAM TOWNSHIP, LIVINGSTON COUNTY, MICHIGAN:
DNR CONCRETE MONUMENT WITH ALUMINUM DNR CAP (DONALD BISSELL 10/89).

N60E	SPIKE AND REMON TAG ON SE SIDE OF NORTHERLY OF TRIPLE 16" HICKORYS	46.95'
S80°E	SPIKE AND REMON TAG ON NORTH SIDE OF 16" OAK	130.48'
N05°E	SPIKE AND REMON TAG ON EAST SIDE OF 4" OAK	91.95'
S60°E	SPIKE AND REMON TAG ON SOUTH SIDE OF 10" HICKORY	69.37'

Signed by *Jack K. Smith* Date 9-15-2000
P.A. 345 1990, APPROVED BY LIVINGSTON COUNTY
Surveyor's Michigan License No. 35998 PER GROUP ON 2-2-2000, CO. REP JED

