

SURVEY & REMONUMENTATION

FEB 26 2001

SECTION

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

FILED

For corners in
LIVINGSTON
(County)

Located in: GREEN OAK Corner Code #

2000 OCT 19 A 10:31

NANCY HAVILAND
REGISTER OF DEEDS
LIVINGSTON COUNTY, MI.
48843

- | | | | |
|---------------------------------------|------|------|------|
| 1. Public Land Survey | T 1N | R 6E | G-10 |
| | T | R | |
| | T | R | |
| | T | R | |
| 2. Property Controlling
in Section | S | T | R |
| | S | T | R |
| 3. Miscellaneous
Property in Sec. | S | T | R |
| | S | T | R |

q- LSC #1307M
Register of Deeds Stamp and File Number

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

I, Bryan L. Boss, in a field survey on APRIL 13, 2000, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefor as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below.

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K
2		6	5		4		3		2		
3											
4		7	8		9		10		11		
5											
6		18	17		16		15		14		
7											
8		19	20		21		22		23		
9											
10		30	29		28		27		26		
11											
12		31	32		33		34		35		
13											

- A. Description of original monument and accessories and/or subsequent restoration:

1823 BY S. SIBLEY, DEPUTY SURVEYOR
SET POST
W. OAK 12" N 28°E 2.21 CHAINS

- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

FOUND 1/2" IRON +/- 5' FROM EAST EDGE OF MARSHALL ROAD
ALSO FOUND 5/8" PIPE 2.85' EAST OF 1/2" IRON


- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

SET 36" PIPE AND BRASS CAP STAMPED
"LIVINGSTON COUNTY REMONUMENTATION
CORNER"
N30°E 32.70' SET REMON NAIL/TAG W/SIDE P.
POLE
EAST 33.00' FOUND MONUMENT
S45°W 70.78' SET REMON NAIL/TAG SE/SIDE 12"
TWIN MAPLE
WEST 55.09' FOUND IRON
N60°W 65.07' SET REMON NAIL/TAG S/SIDE 10"
MAPLE

EAST 2.85' FOUND 5/8" PIPE

P.A. 345 1990, APPROVED BY LIVINGSTON COUNTY

PEER GROUP ON 4-5-2000 CO. REP JED



Signed by [Signature]

Date Sept. 5, 2000

Surveyor's Michigan License No. 29238