

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Livingston
(County)

Located In:

Corner Code ==

1. Public Land Survey

T 2N R 3E

L-12

T _____ R _____

T _____ R _____

T _____ R _____

2. Property Controlling
in Section

S _____ T _____ R _____

S _____ T _____ R _____

3. Miscellaneous

S _____ T _____ R _____

Property in Sec.

S _____ T _____ R _____

4. Lot No. _____, Recorded Plat _____

5. Private Claims _____

Dec 27 12 22 PM '93
NANCY HAVILAND
REGISTER OF DEEDS
LIVINGSTON COUNTY, MI
48843

FILED

L. S. C. #127m
Register of Deeds Stamp & File Number

I, Darrell D. Hughes, in a field survey on December 17, 19 93,
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the
current manual of survey instructions of the United States Department of the Interior, Bureau of Land
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5
above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a
Court of Law; established, re-established, monumented, re-monumented, recovered, found as
expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

GLO: No original monument set.

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	13		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35				
13													

CLERK OF THE COURT
RECORDS & DEEDS

1993

COMMISSION

*Additional historical information on back of sheet:

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found 1/2" iron rod (Boss cap)

D. Description of monument for corner and accessories established to perpetuate locating the position of the corner:


L-12, T2N, R3E, IOSCO, set corner with 1-1/4" X 36" iron pipe, affixed
with 2" dia. brass cap, stamped "Livingston Co. Monumentation Corner,
P.S. 19834, 13' N. of cl E/W ditch, 22' E. of cl N/S ditch and is
accepted as the best available evidence of the position of the corner.
This position was not established by the original government surveyors.
080 DEG. 24.95' SET NAIL/TAG S/S 8" POPLAR.
210 DEG. 29.33' SET NAIL/TAG W/S 10" POPLAR.
273 DEG. 11.72' SET NAIL/TAG S/S 12" ELM.
327 DEG. 19.58' SET NAIL/TAG NE/S 12" ELM.
355 DEG. 0.39' FD. 1/2" IRON ROD (BOSS).

Signed by Darrell D. Hughes Date December 27, 1993

Surveyor's Michigan License No. 19834

Approved by Liv. Co. Peer Group: December 11, 1993

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS: JAN. 28, 1971
REVISED MAY 14, 1975
REVISED JAN., 1983



IOSCO TOWNSHIP, T2N, R3E

L-12, CENTER OF SECTION 36

FIELD 11-29-1993 D.D.HUGHES AND ASSOCIATES, FOWLERVILLE

Found 1/2" iron rod (Boss cap) at NE cor. 3-way ditch, no witness' found.

Corner not set by original U.S. surveyors.

1861, E.N.Fairchilds, County Surveyor, divided Section 36. Shows 79.58 chains (5252.28') from S1/4 to N1/4, also 79.09 chains (5219.94') from W1/4 to E1/4.

1976, Boss ran extensive traverse for all of Section 36 and into the East 1/2 of Section 35. Set 1/2" iron rod at intersection of 1/4 lines.

1976, Boss files Act 74

1990, Matt Brady shows corner in survey. no witness'

no occupation found in any direction.