

MAR 17 2000

SECTION

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

FILED

For corners in

LIVINGSTON
(County)

Located In:

Corner Code #

1. Public Land Survey

T 2 N R 4 E

G-08

2. Property Controlling
in Section

S

T

R

E

3. Miscellaneous
Property in Sec.

S

T

R

E

S

T

R

E

1999 MAY 21 A 9:22

NANCY HAVILAND
REGISTER OF DEEDS
LIVINGSTON COUNTY, MI.
48843

L.S.C. #1016m

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____

5. Private Claims _____

I, JACK K SMITH, in a field survey on APRIL 30, 1999 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

GLO 1825 SIBLEY SET POST
BLACK OAK 13 S 69°W 13.9'
WHITE OAK 16 S 38° E 21.8'

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

FOUND 1/2" REROD 3.5' WEST OF THE CENTER LINE OF COUNTY FARM FROM PREVIOUS WITNESSES. THIS POSITION IS THE ONLY ONE THAT APPEARS TO HAVE BEEN USED.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

G-08 EAST 1/4 CORNER SECTIONS 21 AND WEST 1/4 CORNER SECTION 22, T2N, R4E, MARION TOWNSHIP, LIVINGSTON COUNTY, MICHIGAN:
SET 1 1/4" X 36" STEEL PIPE WITH 6" BREAK OFF SECTION WITH LIVINGSTON COUNTY REMONUMENTATION BRASS CAP WITH SURVEYOR #35999 IN MONUMENT BOX.

N87°W NAIL WITH LIVINGSTON COUNTY REMON TAG IN SOUTH SIDE 15" MAPLE
S51°W NAIL WITH LIVINGSTON COUNTY REMON TAG IN NORTH SIDE DBL. 16" ELM
S36°E NAIL WITH LIVINGSTON COUNTY REMON TAG IN WEST SIDE 5" CEDAR
N75°E NAIL WITH LIVINGSTON COUNTY REMON TAG IN NORTH SIDE 24" ELM

Signed by [Signature]

Date 5-10-1999

Surveyor's Michigan License No. 35999

1	A	B	C	D	E	F	G	H	I	J	K	L	M
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		19		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

38.74'
37.00'
51.50'
36.75'



FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 2
REVISED MAY 14, 1975
REVISED JAN. 1983
REVISED OCT. 1995

P.A. 345 1990, APPROVED BY LIVINGSTON COUNTY
PEER GROUP ON 4-21-1999, CO. REP [Signature]