

SURVEY & REMONUMENTATION

DEC 13 1993

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in COMMISSION

Livingston
(County)

Located In:

Corner Code ##

1. Public Land Survey

T 2N R 4E

M13

2. Property Controlling in Section

S

T R

3. Miscellaneous Property in Sec.

S

T R

4. Lot No. , Recorded Plat

5. Private Claims

Nov 29 3 37 PM '93
HARCY HAVILAND
REGISTER OF DEEDS
LIVINGSTON COUNTY, MI
48843

RECORDED
FILED

L.S.C.#54m

Register of Deeds Stamp & File Number

I, Darrell D Hughes in a field survey on October 22, 19 93, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

GLO survey notes: April 15, 1825

GLO witnesses: B0 16-S81W-.72 ch

W0 12-S16E-.26 ch

Additional historical data on rear of sheet:

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
Found 1/2" I. Rod on North edge of gravel road.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

M-13: SE cor. Section 36, T2N-R4E, reset with 1 1/4" X 36" breakaway I. Pipe with Liv. Co. brass cap on top.

S81E-39.15'-sp S/s 12" Oak

S72E-58.62'-sp S/s 15" Oak

S25E-79.12'-sp N/s 10" pine

S10W-40.73'-sp E/s 38" W Oak

S5W-38.71'-1/2" I. Rod w/cap

N52W-48.69'-ctr. 3" dia Consumers Power Gas line marker

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

Signed by

Darrell D Hughes

Surveyor's Michigan License No.

19834

Approved by Liv. Co. Peer Group: Oct. 30, 1993

Date

11-29-93

October 23, 1993

M-13: SE Cor. Sec. 36 Marion Twp. Liv. Co. MI

Found $\frac{1}{2}$ " iron rod at North edge of gravel road (bent Westerly). Earliest known witnesses by County surveyors, date unknown, but a previous witness of S2W-.61 lks. (40.26') 18" W.Oak also measures 40.26', but tree is about 34" now. All witnesses by Boss Engineering dated 1981, 1990 are to the found iron. All witnesses by Garlock dated 1969 and 1973 are to the found iron. Act 74's filed by both Boss Engineering 1992 and Garlock 1973. Gas line by Consumers Power may have removed previous witnesses Northeasterly and Southwesterly of Corner. Old occupation exists to North and South, center line of road to West and road angles Southeasterly to East around low areas. Surveys in Marion and Putnam Twp. are tied to this Corner as an old Co. Surveyor witness to NW Cor. Sec. 6 Hamburg Twp. Therefore I believe this to be a Corner common to four Townships. Sweep of the area found no additional irons. Woods found in NW and SW quadrants and several trees in NE and SE quadrants. Road surface is gravel.