

SURVEY &  
REMONUMENTATION

FEB 25 1999

SECTION

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

FILED

For corners in

LIVINGSTON

(County)

Located In:

Corner Code #

1. Public Land Survey

T R  
T R  
T R  
T R

2. Property Controlling  
in Section

S T R  
S T R

3. Miscellaneous  
Property in Sec.

S10/15 T2N R4E  
S9/16 T2N R4E

001  
002

1998 OCT 14 P 2:10

NANCY HAVILAND  
REGISTER OF DEEDS  
LIVINGSTON COUNTY, MI.  
48843

LSC 900M

Register of Deeds Stamp & File Number

4. Lot No. , Recorded Plat

5. Private Claims

I, CHARLES E. GARLOCK in a field survey on AUG 11, 1998 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

GLO SURVEY DATED APRIL 15, 1825, BY S SIBLEY  
GLO WITNESSES: N33W-61 LKS-4" SPRUCE  
S10½W-13 LKS-3" SPRUCE

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

CORNER FALLS IN A SWAMP; SET WITNESS PIPES AT THE 1/8 CORNERS NEXT EAST AND WEST OF THIS SECTION CORNER. SEE REVERSE SIDE FOR METHOD OF WITNESSING THE SECTION CORNER AND METHOD OF ESTABLISHING SAID CORNER.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

001: S 1/8 COR. SW1/4 SEC. 10  
SET MON. BOX AND 1 1/4" X 36" I. PIPE W/LIV.  
CO. REMON BRASS CAP ON TOP IN PLACE OF THE FD.  
RR SPIKE  
N25W-59.13'-SP 7 TAG E/S 36" OAK  
N15E-88.78'-SP & TAG W/S 16" HICKORY  
S15E-44.47'-SP & TAG W/S DBL 8" OAK  
S35W-58.97'-SP & TAG W/S 10" LOCUST  
S89°38'19"W 1318.37' TO COR. 6-5

002: S 1/8 COR. SE 1/4 SEC. 9  
SET REMON BRASS CAP IN TOP OF WELL PT.  
S5E-2.42'-SP & TAG E/S 26" OAK  
N10W-11.75'-SP & TAG E/S 26" OAK  
N75W-22.25'-SP & TAG N/S 14" HICKORY  
N60E-91.02'-91.02'-SE COR. HOUSE #3200  
S89°43'12"E, 1324.49' TO COR. 6-5

Signed by

Charles E. Garlock

Date AUGUST 12, 1998

Surveyor's Michigan License No.

14762

PA. 345 1999, APPROVED BY LIVINGSTON COUNTY  
PEER GROUP ON 5/20/98, CO. REP JED

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971  
REVISED MAY 14, 1975  
REVISED JAN., 1983  
REVISED OCT., 1995

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

