

SURVEY & REMONUMENTATION

FEB 26 2001

FILED

SECTION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

2000 NOV -8 A 9:43

For corners in

LIVINGSTON
(County)

Located In:

Corner Code #

NANCY HAVILAND
REGISTER OF DEEDS
LIVINGSTON COUNTY, MI.
48843

1. Public Land Survey

T 2 N R 4 E F-11

T R

T R

T R

2. Property Controlling
in Section

S T R

S T R

3. Miscellaneous
Property in Sec.

S T R

S T R

LSC #1353m

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____

5. Private Claims _____

I, JACK K SMITH, in a field survey on OCT. 4, 2000 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

1	A	B	C	D	E	F	G	H	I	J	K	L	M
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

A. Description of original monument and accessories and/or subsequent restoration:

GLO 1825 SIBLEY SET POST
TAMARACK 6" S65°E 33.00'
TAMARACK 10" N16°W 95.04'

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

F-11 IS MARKED BY 1 1/4" STEEL PIPE SET BY DARRELL HUGHES (2000) IN THE CENTER OF A NORTH-SOUTH CREEK AND ON FENCE REMNANTS AND TREE ROWS EAST AND WEST.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

F-11 SOUTHWEST CORNER SECTION 21, T2N, R4E, MARION TOWNSHIP, LIVINGSTON COUNTY, MICHIGAN:
USED THE EXISTING 1 1/4" X 36" STEEL PIPE WITH LIVINGSTON COUNTY REMONUMENTATION BRASS CAP WITH SURVEYOR #35999.

EAST SPIKE AND LIVINGSTON COUNTY REMON TAG IN SOUTH SIDE OF TWIN 6" HAWTHORNES 39.05'
EAST FOUND IRON 10.00'
S60°W SPIKE AND LIVINGSTON COUNTY REMON TAG IN NW SIDE OF A 10" MAPLE 16.51'
N70°W SPIKE AND LIVINGSTON COUNTY REMON TAG IN SOUTH SIDE OF A 8" CHERRY 34.60'
N33°E SPIKE AND LIVINGSTON COUNTY REMON TAG IN SE SIDE OF A 16" CHERRY 67.64'

Signed by

Date

Surveyor's Michigan License No. 35999



FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS JAN. 24, 1971
REVISED MAY 14, 1975

PA. 345 1990, APPROVED BY LIVINGSTON COUNTY
PEER GROUP ON 9-20-2000 CO. REP JED