## SURVEY & REMONUMENTATION

FEB 26 2001

FILED

9	EC	Ti	$\cap$	A
~				IV

## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74 Mich. P.A. 1970

		i mily nequirem	one of wor 14, mion.	1 171 1070									
	corners in IVINGSTON			9		7	100 N	OV 2	29 .	A	9: 5	0	
	(County)	Located in: GENOA	Corner Code #	1			NA:	NCY	HAVI	LAN:	n		
1.	Public Land Survey	T <u>2N</u> R 5E T R	C-7			LI	REG	STEI	R OF N COU 1843	DEEL JNTY	ic		
2	Property Controlling	T R T R						15	C #1	384	m		
۷.	in Section	S T R S T R	where you is deviced by an angeline and an arrange of the state of the						0 ,, 1	.00 1	•••		
3.		_											
٠.	Property in Sec.	SR		Register	of	Dec	ds S	tamp	and	File I	Num	ber	
4.	Lot No,	Recorded Plat					•						
5.	Private Claims				(	A . B	<u>_ç</u>	DΕ	F	G H		+	Ķ i
			•		2	_!		!	_!_	$\prod_{i=1}^{n}$	丄	- 1 - 2	上
			•		3	9—		اً ا		١í	丄	<u>i</u>	L
ı.	Bryan L. Boss	, in a field survey on	FEBRUARY 28, 2000		4	Ţ	$\perp$				$\perp$	11	L
-,	hereby certify that under re	equirements of P.A. 74, Michigan P.	A. of 1970, the corner poi	nts mentioned	5			Ĭ	<u> </u>		$\perp$		L
in I	ines 1 and 2 above were	e in conformance with regulations	and rules therefor as re-	quired in the	8							<u> </u>	_
		structions of the United States De			Ť	<b>□18</b>	T	Ϋ́Т	-16-	Τï	$\top$	1	Т
		f a Court of Law and/or that the co			1		_	1	$\neg$	$\top$	$\neg$	1	T
		with the rules of the Michigan Boar re-established, monumented, re-			8	19		20 <b>-</b>	-21	十沿	-	-23 <del></del>	十
	ressed below.	To-ostabilistica, monamentea, 10-	monumented, 1000vered,	100110 03	9	$\vdash$		<del>                                     </del>		++		+-	╁
NO	TE: Not more than 4 c	corners, all in the same town and	i range, may be recorde	d	10	<b>—</b> 30	+	29 -	- 2B	+- 2 <sup>7</sup>	'+	-26-	T
	on this certificate	•	, •		11			1 1	+	TT	_	1	†
			•		12	-3	+	32 <del>-  </del>	— j3 —	<del>-</del> 34	·	- 35 -	+
Α.	Description of original	monument and accessories and	or subsequent restorati	on:	13	ш						1	-
	1823 BY S. SIBLEY, DEF SET POST					•							
	B. OAK 10" N 18° E 2.13 W. OAK 6" N 88° E 1.09												
		:		•									
В.	Description of corner e	evidence found and/or method ap	oplied in restoring or ree	stabli <mark>shi</mark> ng c	orn	er:							

FOUND 1/2" IRON BELOW RAILROAD SPIKE +/- 4" SOUTH OF CENTER LINE CROOKED LAKE RD

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

SET 1 1/4" X 30" PIPE WITH 6" BREAKAWAY PIPE AND A BRASS CAP STAMPED "LIVINGSTON COUNTY REMONUMENTATION CORNER". N 80° E 58.60' WEST RAIL OF TRACKS PERPENDICULAR TO CORNER N 80° E 75.83' SET REMON NAIL/TAG S/SIDE RAILROAD CROSSING SIGN S 80° E 58.35' SET REMON NAIL/TAG N/SIDE RAILROAD CROSSING SIGN S 45° E 118.01' SET REMON NAIL/TAG W/SIDE POWER POLE

يان الحياس

S 60° W 69.34' SET REMON NAIL/TAG N/SIDE 10" CHERRY N 5° W 125.75' SET REMON NAIL/TAG E/SIDE POWR POLE

P.A. 345 1990, APPROVED BY LIVINGSTON COUNTY
PEER GROUP ON 2-2-2000 CO. REP JED

SRYAN L.
BOSS
Land Surveyor
NO.
29238

Signed by Sugar	1/200	Date	Seat. 5
		Date	
Surveyor's Michigan License No.	29238		

2000