SURVEY & REMONUMENTATION

FEB 26 2001

FILED

LAND CORNER	RECORDAT	ION CERTI	FICATE
Filing Requirems	nt of Act 74	L Mich P	A. 1970

For	SECTION corners in	.Fillig Requireme	int of Act 74, when,	F.A. 1370		700	n nc	T 14	ο 4	. In			
	IVINGSTON	Located in: BRIGHTON	Corner Code #						9 4			ı	
	(County)					R.	MANO	YH	AVIL	AND	_		
1. Public Land Survey		T 2N R 6E B-9 T			REGISTER OF DEEDS LIVINGSTON COUNTY, MI. 48843								
		TR TR											
2.	Property Controlling	STR		0/									
	in Section	STR		191			#12						
3.	Miscellaneous Property in Sec.	S 19 T 2N R GE S 19 T 2N R GE	005	Register	r of	Des	eds S	tam	o and	File	Nu	mbei	r
	•	Recorded Plat					_						v
5.	Private Claims				- 1	<u> </u>	Ť	řŤ	f	ŤΤ	7	Ť	Ť
					2	ģ		<u> </u>		+-	ì₩	—į-	-
	m1 m		DDU 44 0000		3	\neg		Ħ	-	\top	\Box		7
	Bryan L. Boss	, in a field survey onA	PRIL 14, 2000		4	-ż	+	ا ا	_ • -	+19	7	— 11 - I	٦
		requirements of P.A. 74, Michigan P.A re in conformance with regulations			5	+	\dashv	\vdash	1	+	\Box	+	_
		nstructions of the United States Dep		•	6	-18		įγ	—16-	+-1	5	-14·	ᅥ
Mai	nagement or by a decree	of a Court of Law and/or that the con	rner points mentioned in li	nes 3,4 and 5		-	\dashv	\vdash		+	H		_
		e with the rules of the Michigan Board , re-established, monumented, re-r			8	- 1 g	+	20-	— 21 —	+-2	2	— 23 I	_
	ressed below,	, re-established, monumented, re-	monumented, recovered,	iouna as	9	•	•	\vdash		+			
NOTE: Not more than 4 corners, all in the same town and range, may be recorded			10	30		29-	— 28-	- 	7	<u>2</u> 6	٦		
	on this certificate	9.	•		11		\dashv	1		+-	Н	一十	-
		•			12	-3j	+	32-	- 33-	十3	4-	-35 I	-
A.	Description of origina	il monument and accessories and/	or subsequent restoration	on:	13	Щ.				—	L		_
	1823 BY S. SIBLEY, DE SET POST	:PUTY SURVEYOR											
	W. OAK 6" S 44 1/2 W 4 B. OAK 10" N 25°E 54 L												
	•												
В.	·	evidence found and/or method ap		stablishing c	orn	er:							
		TED UNDER A HOUSE. THE L'OCATIO											

4 PAGE 3 L.C.R.. REFERENCE POINTS WERE ESTABLISHED AT TWO POINTS:

60\$ "NORTH" FOUND 3/4" IRON PIPE NORTH NORTH 30.63"

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

NORTH (005) SET 1 1/4" X 36" PIPE AND BRASS CAP STAMPED "LIVINGSTON COUNTY REMONUMENTATION

WITNESS" N 5°E 34.54' SET REMON NAIL/TAG W/SIDE 12" OAK

EAST 33.57' SET REMON NAIL/TAG N/SIDE 18" OAK SOUTH 9.54' NW CORNER CONCRETE STEPS WEST 9.71' SET REMON NAIL/TAG S/SIDE 18" OAK

WEST (006) SET 1 1/4" X 36" PIPE AND BRASS CAP STAMPED "LIVINGSTON COUNTY REMONUMENTATION

NORTH 23,00' SET REMON NAIL/TAG E/SIDE 14"

ASPEN

N85°E 8.31' SET REMON NAIL/TAG S/SIDE 10" ASPEN

S85°E 4.56' SET REMON NAIL/TAG N/SIDE 10"

ASPEN

N45°W 13.65' SET REMON NAIL/TAG S/SIDE 14" **ASPEN**

MICHIG BRYAN L. BO93 nd Surveyor NO. 29238 CAND SU

RA, 345 1900, APPROVED BY LIVINGSTON COUNTY PEER GROUP ON 4-5-2000 CO. REP JED

Signed by Surveyor's Michigan License No.

29238